

PAR COURRIEL

Le 27 juin 2025

DEMANDEUR

N/Réf : 202506-03

Objet : Demande d'accès à l'information

Madame,

Nous donnons suite à votre demande d'accès à l'information reçue le 2 juin 2025.

La recherche a permis de repérer des documents concernant votre demande qui vous sont accessibles. Vous les trouverez ci-joints.

Sur réception de ces documents, vous remarquerez que nous avons soustrait certains renseignements, comme le permet l'article 14 de la Loi sur l'accès aux documents des organismes publics et sur la protection des renseignements personnels (RLRQ, chapitre A-2.1). En effet, nous avons retranché les renseignements personnels, lesquels sont confidentiels au sens des articles 53 et 54 de cette loi.

Nous vous indiquons que vous pouvez demander à la Commission d'accès à l'information de réviser cette décision. Vous trouverez ci-joint une note explicative concernant l'exercice de ce recours ainsi qu'une copie des articles précités.

Veuillez agréer, Madame, l'expression de nos sentiments les meilleurs.

La responsable substitut de l'accès à l'information,

Original signé par

Chantal Turgeon-Pelchat

p. j. : 3

| Site_nm | Étiquette PTSC | Rapport d'inventaire | Site_type | x_coord | y_coord | COMUNITY | TRAPLINE | CAT | Nom de la Consultation |
|-----------|----------------|----------------------------------|--------------------|------------|-----------|------------|-----------|--------|------------------------|
| CH/6-050 | 0600-2009-417 | | Mining exploration | -73,796714 | 53,929084 | Chisasibi | FG21/CH21 | <Null> | CH1/33H |
| CH/6-052 | 0600-2009-418 | | Mining exploration | -73,699912 | 53,929566 | Chisasibi | FG21/CH21 | <Null> | CH3/33H |
| CH/6-062 | 0600-2009-419 | | Mining exploration | -71,241312 | 54,61933 | Chisasibi | FG31/CH31 | <Null> | CH2/23L |
| CH/6-073 | 0600-2009-420 | | Mining exploration | -77,753986 | 53,499334 | Chisasibi | VC04/CH36 | <Null> | CH25/33F |
| CH/6-080 | 0600-2009-421 | | Mining exploration | -77,262594 | 53,408021 | Chisasibi | VC06/CH38 | <Null> | CH02/33F |
| CH/6-082 | 0600-2009-422 | | Mining exploration | -77,570807 | 53,372321 | Chisasibi | VC06/CH38 | <Null> | CH04/33F |
| CH/6-083 | 0600-2009-423 | | Mining exploration | -77,478433 | 53,370542 | Chisasibi | VC06/CH38 | <Null> | CH06/33F |
| CH/6-085 | 0600-2009-424 | | Mining exploration | -77,41366 | 53,39054 | Chisasibi | VC06/CH38 | <Null> | CH08/33F |
| CH/6-086 | 0600-2009-425 | | Mining exploration | -77,647992 | 53,352792 | Chisasibi | VC06/CH38 | CAT II | CH09/33F |
| CH/6-087 | 0600-2009-426 | | Mining exploration | -77,603352 | 53,337178 | Chisasibi | VC06/CH38 | <Null> | CH10/33F |
| CH/6-090 | 0600-2009-427 | | Mining exploration | -78,053449 | 53,270689 | Chisasibi | VC06/CH38 | CAT II | CH01/33E |
| ET/6-002 | 0600-2009-428 | | Mining exploration | -77,503491 | 52,44632 | Eastmain | VC33 | <Null> | E09/33C |
| ET/6-003 | 0600-2009-429 | | Mining exploration | -77,664534 | 52,359688 | Eastmain | VC33 | CAT II | E10/33C |
| ET/6-004 | 0600-2009-430 | | Mining exploration | -77,705701 | 52,361458 | Eastmain | VC33 | CAT II | E11/33C |
| ET/6-007 | 0600-2009-431 | | Mining exploration | -76,492339 | 52,483323 | Eastmain | VC35 | <Null> | E19/33C |
| ET/6-009 | 0600-2009-432 | | Mining exploration | -76,593829 | 52,213467 | Eastmain | VC35 | <Null> | E01/33C |
| ET/6-014 | 0600-2009-433 | | Mining exploration | -75,895311 | 52,211917 | Eastmain | VC37 | <Null> | E01/33B |
| ET/6-015 | 0600-2009-434 | | Mining exploration | -75,723843 | 52,192743 | Eastmain | VC37 | <Null> | E02/33B |
| ET/6-016 | 0600-2009-435 | | Mining exploration | -75,66303 | 52,185639 | Eastmain | VC37 | <Null> | E03/33B |
| ET/6-019 | 0600-2009-436 | | Mining exploration | -76,366324 | 52,247289 | Eastmain | VC35 | <Null> | E04/33C |
| ET/6-020 | 0600-2009-437 | | Mining exploration | -76,389833 | 52,213071 | Eastmain | RE01 | <Null> | E05/33C |
| ET/6-021 | 0600-2009-438 | | Mining exploration | -76,249884 | 52,209607 | Eastmain | RE01 | <Null> | E06/33C |
| ET/6-024 | 0600-2009-439 | | Mining exploration | -77,095957 | 52,320529 | Eastmain | VC33 | <Null> | E13/33C |
| MI/21-327 | 0600-2009-440 | MI6-062_MI6-069_MI21-326.docx | Mining exploration | -72,198826 | 51,882939 | | | | |
| MI/6-017 | 0600-2009-441 | | Mining exploration | -71,227221 | 53,616994 | Mistissini | M01 | <Null> | MS25/23E |
| MI/6-026 | 0600-2009-442 | | Mining exploration | -70,524656 | 53,249547 | Mistissini | M07 | <Null> | MS16/23E |
| MI/6-034 | 0600-2009-443 | | Mining exploration | -74,339487 | 52,787928 | Mistissini | M08 | <Null> | MS04/33B |
| MI/6-042 | 0600-2009-444 | | Mining exploration | -71,932635 | 52,900551 | Mistissini | M11 | <Null> | MS01/23D |
| MI/6-045 | 0600-2009-445 | | Mining exploration | -72,133001 | 52,536125 | | | | |
| MI/6-046 | 0600-2009-446 | | Mining exploration | -72,261654 | 52,641716 | Mistissini | M11 | <Null> | MS04/33A |
| MI/6-049 | 0600-2009-448 | | Mining exploration | -71,279557 | 52,673655 | Mistissini | M12 | <Null> | MS35/23D |
| MI/6-062 | 0600-2009-450 | | Mining exploration | -72,099168 | 52,343435 | Mistissini | M16 | <Null> | MS20/33A |
| MI/6-066 | 0600-2009-451 | | Mining exploration | -72,135768 | 52,45577 | Mistissini | M16 | <Null> | MS24/33A |
| MI/6-067 | 0600-2009-452 | | Mining exploration | -72,122033 | 52,454881 | Mistissini | M16 | <Null> | MS25/33A |
| MI/6-068 | 0600-2009-453 | | Mining exploration | -72,132659 | 52,151526 | Mistissini | M16 | <Null> | MS26/33A |
| MI/6-069 | 0600-2009-454 | MI6-062_MI6-069_MI21-326.docx | Mining exploration | -71,802475 | 52,583301 | Mistissini | M16 | <Null> | MS45/23D |
| MI/6-070 | 0600-2009-455 | | Mining exploration | -71,947478 | 52,353595 | Mistissini | M16 | <Null> | MS46/23D |
| MI/6-071 | 0600-2009-456 | | Mining exploration | -71,838185 | 52,643327 | Mistissini | M16 | <Null> | MS47/23D |
| MI/6-074 | 0600-2009-457 | | Mining exploration | -71,904142 | 52,500479 | Mistissini | M16 | <Null> | MS50/23D |
| MI/6-075 | 0600-2009-458 | | Mining exploration | -71,862198 | 52,225492 | Mistissini | M17 | <Null> | MS30/23D |
| MI/6-076 | 0600-2009-459 | | Mining exploration | -71,861485 | 52,147133 | Mistissini | M17 | <Null> | MS31/23D |
| MI/6-077 | 0600-2009-460 | | Mining exploration | -71,744848 | 52,067581 | Mistissini | M17 | <Null> | MS32/23D |
| MI/6-079 | 0600-2009-461 | | Mining exploration | -71,823187 | 51,92158 | Mistissini | M17 | <Null> | MS07/22M |
| MI/6-084 | 0600-2009-462 | Mistissini MI6-084.pdf | Mining exploration | -71,409346 | 52,076566 | Mistissini | M17B | <Null> | MS06/23D |
| MI/6-085 | 0600-2009-463 | | Mining exploration | -71,056608 | 52,278749 | | | | |
| MI/6-087 | 0600-2009-464 | Abandoned Mine sites_MI6-087.pdf | Mining exploration | -70,903896 | 52,110132 | Mistissini | M17B | <Null> | MS09/23D |
| MI/6-090 | 0600-2009-465 | Abandoned Mine sites_MI6-090.pdf | Mining exploration | -71,11101 | 52,311566 | Mistissini | M17B | <Null> | MS12/23D |
| MI/6-091 | 0600-2009-466 | Mistissini MI6-091.pdf | Mining exploration | -70,95365 | 52,418069 | Mistissini | M17B | <Null> | MS13/23D |
| MI/6-101 | 0600-2009-467 | | Mining exploration | -71,314277 | 52,057762 | | | | |
| MI/6-103 | 0600-2009-468 | Mistissini MI6-103.pdf | Mining exploration | -71,622961 | 51,705982 | Mistissini | M17C | <Null> | MS01/22M |
| MI/6-104 | 0600-2009-469 | Mistissini MI6-104.pdf | Mining exploration | -71,714257 | 51,707201 | Mistissini | M17C | <Null> | MS02/22M |

| | | | | | | | | | |
|-----------|---------------|----------------------------------|--------------------|------------|-----------|------------|------|--------|-----------------------|
| MI/6-106 | 0600-2009-470 | Abandoned Mine sites_MI6-106.pdf | Mining exploration | -71,912527 | 51,793459 | Mistissini | M17C | <Null> | MS04/22M |
| MI/6-107 | 0600-2009-471 | Mistissini MI6-107.pdf | Mining exploration | -71,992299 | 51,784997 | Mistissini | M17C | <Null> | MS05/22M |
| MI/6-108 | 0600-2009-472 | Mistissini MI6-108.pdf | Mining exploration | -71,812881 | 51,886972 | Mistissini | M17C | <Null> | MS06/22M |
| MI/6-109 | 0600-2009-473 | Mistissini MI6-109.pdf | Mining exploration | -71,821115 | 51,865426 | Mistissini | M17C | <Null> | MS10/22M |
| MI/6-110 | 0600-2009-474 | Mistissini MI6-110.pdf | Mining exploration | -71,971925 | 51,845106 | Mistissini | M17C | <Null> | MS11/22M |
| MI/6-113 | 0600-2009-475 | Abandoned Mine sites_MI6-113.pdf | Mining exploration | -72,024622 | 51,803648 | Mistissini | M17C | <Null> | MS07/32P |
| MI/6-115 | 0600-2009-476 | | Mining exploration | -72,028578 | 51,946132 | Mistissini | M17C | <Null> | MS09/32P |
| MI/6-120 | 0600-2009-477 | | Mining exploration | -72,676696 | 52,281077 | Mistissini | M23 | <Null> | MS05/33A |
| MI/6-122 | 0600-2009-479 | | Mining exploration | -72,78045 | 52,325415 | Mistissini | M23 | <Null> | MS07/33A |
| MI/6-129 | 0600-2009-480 | | Mining exploration | -72,758631 | 51,459914 | Mistissini | M29 | CAT II | MS11/32P |
| MI/6-130 | 0600-2009-481 | | Mining exploration | -72,740183 | 51,491176 | Mistissini | M29A | CAT II | MS12/32P |
| MI/6-132 | 0600-2009-482 | | Mining exploration | -72,618032 | 51,464406 | Mistissini | M29 | CAT II | MS14/32P |
| MI/6-147 | 0600-2009-483 | | Mining exploration | -73,815408 | 51,021246 | Mistissini | M35 | CAT II | MS31/32P |
| MI/6-161 | 0600-2009-484 | | Mining exploration | -72,840366 | 51,143383 | Mistissini | M42 | <Null> | MS01/32P |
| MI/6-164 | 0600-2009-485 | | Mining exploration | -72,652616 | 51,236675 | | | | |
| MI/6-166 | 0600-2009-486 | | Mining exploration | -73,089985 | 51,002727 | Mistissini | M42A | <Null> | MS25/32P |
| MI/6-171 | 0600-2009-487 | | Mining exploration | -73,234988 | 50,913050 | | | | |
| MI/6-172 | 0600-2009-488 | | Mining exploration | -73,046527 | 50,973676 | | | | |
| MI/6-173 | 0600-2009-489 | | Mining exploration | -72,827065 | 51,095879 | Mistissini | M42 | <Null> | MS51/32P |
| MI/6-174 | 0600-2009-490 | | Mining exploration | -72,727251 | 51,135564 | Mistissini | M42 | <Null> | MS52/32P |
| MI/6-180 | 0600-2009-491 | | Mining exploration | -75,382369 | 50,587424 | Mistissini | M47 | <Null> | MS25/32J |
| MI/6-182 | 0600-2009-492 | | Mining exploration | -75,531924 | 50,414122 | Mistissini | M47A | <Null> | MS11/32J |
| MI/6-189 | 0600-2009-493 | | Mining exploration | -73,833852 | 50,185077 | Mistissini | M51 | <Null> | MS10/32I |
| MI/6-191 | 0600-2009-494 | | Mining exploration | -73,775198 | 50,268503 | Mistissini | M51 | CAT II | MS12/32I |
| MI/6-199 | 0600-2009-496 | | Mining exploration | -73,977016 | 50,157197 | Mistissini | M56 | <Null> | MS02/32I |
| MI/7-205 | 0600-2009-497 | | Mining exploration | -74,507942 | 52,10827 | Mistissini | M14 | <Null> | MI51/33B |
| MI/7-208 | 0600-2009-498 | | Mining exploration | -74,971289 | 52,403371 | Mistissini | M14A | <Null> | MI33/33B |
| MI/7-223 | 0600-2009-499 | | Mining exploration | -71,490337 | 52,258071 | Mistissini | M17 | <Null> | MI103/23D |
| MI/7-225 | 0600-2009-500 | | Mining exploration | -71,252401 | 52,359454 | Mistissini | M17A | <Null> | MI104/23D |
| MI/7-227 | 0600-2009-501 | | Mining exploration | -71,204305 | 52,151675 | Mistissini | M17B | <Null> | MI107/23D |
| MI/7-229 | 0600-2009-502 | | Mining exploration | -72,092166 | 51,956452 | Mistissini | M17C | <Null> | MI103/32P |
| MI/7-236 | 0600-2009-503 | | Mining exploration | -73,929735 | 51,931025 | Mistissini | M22 | <Null> | MI151/32P |
| MI/7-237 | 0600-2009-504 | | Mining exploration | -73,841159 | 51,810368 | Mistissini | M22 | CAT II | MI152/32P |
| MI/7-239 | 0600-2009-505 | | Mining exploration | -75,1837 | 51,818119 | Mistissini | M25 | <Null> | MI120/32O |
| MI/7-251 | 0600-2009-506 | | Mining exploration | -73,129667 | 51,682964 | Mistissini | M28 | CAT II | MI112/32P |
| MI/7-255 | 0600-2009-508 | | Mining exploration | -73,463423 | 51,366501 | Mistissini | M28A | CAT II | MI116/32P |
| MI/7-257 | 0600-2009-509 | | Mining exploration | -73,295472 | 51,474087 | Mistissini | M28A | CAT II | MI118/32P |
| MI/7-265 | 0600-2009-510 | | Mining exploration | -72,685278 | 51,213377 | Mistissini | M36 | <Null> | MI100/32P |
| MI/7-276B | 0600-2009-512 | | Mining exploration | -74,745204 | 50,729538 | Mistissini | M40 | <Null> | MI45/32J |
| MI/7-278 | 0600-2009-513 | | Mining exploration | -74,566169 | 50,869089 | Mistissini | M40 | <Null> | MI47/32J |
| MI/7-279 | 0600-2009-514 | | Mining exploration | -74,877761 | 50,736703 | Mistissini | M40 | <Null> | MI48/32J |
| MI/7-281 | 0600-2009-515 | | Mining exploration | -74,454455 | 50,682024 | Mistissini | M41 | <Null> | MI50/32J |
| MI/7-293 | 0600-2009-517 | | Mining exploration | -73,702815 | 50,342848 | Mistissini | M51B | CAT II | MI105/32I |
| MI/7-295 | 0600-2009-518 | | Mining exploration | -75,510713 | 52,056678 | Mistissini | M18 | <Null> | MI01/Map M-18 |
| MI/7-304 | 0600-2009-523 | | Mining exploration | -72,652371 | 51,780694 | Mistissini | M29A | CAT II | MI02/32Pne |
| MI/7-305 | 0600-2009-524 | | Mining exploration | -72,484932 | 51,7516 | Mistissini | M29A | CAT II | MI03/32Pne |
| MI/7-306 | 0600-2009-525 | | Mining exploration | -72,763888 | 51,523903 | Mistissini | M29A | CAT II | MI04/32Pne |
| MI/7-307 | 0600-2009-526 | | Mining exploration | -72,642238 | 51,570768 | Mistissini | M29A | CAT II | MI05/32Pne |
| MI/7-308 | 0600-2009-527 | | Mining exploration | -72,782903 | 51,480711 | Mistissini | M29A | CAT II | MI06/General location |
| MI/7-309 | 0600-2009-528 | | Mining exploration | -72,755245 | 51,67215 | Mistissini | M29A | CAT II | MI07/32Pne |
| MI/7-311 | 0600-2009-529 | | Mining exploration | -72,697244 | 51,535511 | Mistissini | M29A | CAT II | MI09/32Pne |
| MI/7-312 | 0600-2009-530 | | Mining exploration | -72,671431 | 51,52026 | Mistissini | M29A | CAT II | MI10/32Pne |
| MI/7-314 | 0600-2009-531 | | Mining exploration | -72,235152 | 51,505796 | Mistissini | M30 | <Null> | MI03/Map M-30 |
| MI/7-316 | 0600-2009-532 | | Mining exploration | -74,634448 | 51,107993 | Mistissini | M39A | <Null> | MI02/32Ose |

| | | | | | | | | | |
|-----------|---------------|----------|--------------------|------------|-----------|----------------|---------|--------|-----------|
| MOB/7-001 | 0600-2009-533 | | Mining exploration | -73,993456 | 50,002624 | Ouje-Bougoumou | O57/M57 | <Null> | MI100/32I |
| MOB/7-002 | 0600-2009-534 | | Mining exploration | -73,975489 | 50,035378 | Ouje-Bougoumou | O57/M57 | <Null> | MI101/32I |
| MOB/7-003 | 0600-2009-535 | | Mining exploration | -73,980196 | 49,974761 | Ouje-Bougoumou | O57/M57 | <Null> | MI102/32I |
| MOB/7-004 | 0600-2009-536 | | Mining exploration | -74,025305 | 49,964104 | Ouje-Bougoumou | O57/M57 | <Null> | MI103/32I |
| MOB/7-005 | 0600-2009-537 | | Mining exploration | -74,016483 | 49,920152 | Ouje-Bougoumou | O57/M57 | <Null> | MI104/32I |
| MOB/7-006 | 0600-2009-538 | | Mining exploration | -74,04565 | 49,918008 | Ouje-Bougoumou | O57/M57 | <Null> | MI104/32I |
| MOB/7-007 | 0600-2009-539 | | Mining exploration | -74,022271 | 49,908262 | Ouje-Bougoumou | O57/M57 | <Null> | MI105/32I |
| MOB/7-017 | 0600-2009-540 | | Mining exploration | -74,237177 | 49,938231 | Ouje-Bougoumou | O57/M57 | <Null> | MI110/32I |
| MOB/7-019 | 0600-2009-541 | | Mining exploration | -74,100383 | 49,98262 | Ouje-Bougoumou | O57/M57 | <Null> | MI112/32I |
| MOB/7-025 | 0600-2009-542 | | Mining exploration | -74,106583 | 49,910266 | Ouje-Bougoumou | O57/M57 | <Null> | MI7/m57 |
| MOB/7-026 | 0600-2009-543 | | Mining exploration | -73,888662 | 49,914356 | Ouje-Bougoumou | O57/M57 | <Null> | MI09/m57 |
| MOB/7-029 | 0600-2009-544 | | Mining exploration | -74,181945 | 49,927836 | Ouje-Bougoumou | O57/M57 | <Null> | MI16/m57 |
| MOB/7-031 | 0600-2009-545 | | Mining exploration | -73,938532 | 50,08359 | Ouje-Bougoumou | O57/M57 | <Null> | OJ1/o57 |
| MOB/7-033 | 0600-2009-546 | | Mining exploration | -73,98967 | 49,830643 | Ouje-Bougoumou | O57/M57 | <Null> | OJ4/o57 |
| NA/6-006 | 0600-2009-547 | | Mining exploration | -77,199479 | 50,772863 | Nemaska | N19 | <Null> | NA128/32K |
| NA/6-013 | 0600-2009-548 | | Mining exploration | -77,37445 | 50,615966 | Nemaska | N20 | <Null> | NA112/32K |
| NA/6-014 | 0600-2009-549 | 2 photos | Mining exploration | -77,566914 | 50,648445 | Nemaska | N20 | <Null> | NA1/32K |
| NA/6-015 | 0600-2009-550 | | Mining exploration | -77,279591 | 50,552906 | Nemaska | N20 | <Null> | NA111/32K |
| NA/6-016 | 0600-2009-551 | | Mining exploration | -77,216243 | 50,59413 | Nemaska | N20 | <Null> | NA110/32K |
| NA/6-027 | 0600-2009-552 | | Mining exploration | -77,321219 | 50,924429 | Nemaska | N21 | <Null> | NA131/32K |
| NA/6-032 | 0600-2009-553 | | Mining exploration | -77,48361 | 51,224845 | Nemaska | N23 | <Null> | NA26/32N |
| NA/6-041 | 0600-2009-554 | | Mining exploration | -76,984672 | 51,315748 | Nemaska | N23 | <Null> | NA111/32N |
| NA/6-070 | 0600-2009-555 | | Mining exploration | -76,090469 | 51,546198 | Nemaska | R18 | <Null> | NA9/32N |
| NA/6-072 | 0600-2009-556 | | Mining exploration | -76,275081 | 51,53686 | Nemaska | R18 | <Null> | NA6/32N |
| NA/6-077 | 0600-2009-557 | | Mining exploration | -76,288765 | 51,526118 | Nemaska | R18 | <Null> | NA7/32N |
| NA/6-093 | 0600-2009-558 | | Mining exploration | -75,876783 | 51,666305 | Nemaska | R18 | <Null> | NA102/32O |
| NA/6-095 | 0600-2009-559 | | Mining exploration | -75,559298 | 51,713044 | Nemaska | R20 | CAT II | NA6/32O |
| NA/6-096 | 0600-2009-560 | | Mining exploration | -75,55714 | 51,700594 | Nemaska | R20 | CAT II | NA5/32O |
| OB/7-012 | 0600-2009-561 | | Mining exploration | -75,206758 | 50,034625 | Ouje-Bougoumou | O53 | CAT II | OJ03/32I |
| OB/7-017 | 0600-2009-562 | | Mining exploration | -74,913879 | 50,007468 | Ouje-Bougoumou | O53 | CAT II | OJ01/32I |
| OB/7-043 | 0600-2009-563 | | Mining exploration | -74,172735 | 49,82171 | Ouje-Bougoumou | O59 | <Null> | MI116/32I |
| OB/7-059 | 0600-2009-564 | | Mining exploration | -74,498134 | 49,476438 | Ouje-Bougoumou | O60 | <Null> | OJ01/32G |
| WJ/6-004 | 0600-2009-565 | | Mining exploration | -77,725107 | 53,189648 | Wemindji | VC12 | CAT II | WJ15/33F |
| WJ/6-008 | 0600-2009-566 | | Mining exploration | -77,229881 | 53,362517 | Wemindji | VC16 | <Null> | WJ03/33F |
| WJ/6-009 | 0600-2009-567 | | Mining exploration | -77,304363 | 53,352605 | Wemindji | VC16 | <Null> | WJ04/33F |
| WJ/6-028 | 0600-2009-568 | | Mining exploration | -76,683029 | 53,407059 | Wemindji | VC20 | <Null> | WJ11/33F |
| WJ/6-032 | 0600-2009-569 | | Mining exploration | -75,874544 | 53,278277 | Wemindji | VC21 | <Null> | WJ05/33G |
| WJ/6-043 | 0600-2009-570 | | Mining exploration | -75,673799 | 53,571383 | Wemindji | VC24 | <Null> | WJ10/33G |
| WJ/6-046 | 0600-2009-571 | | Mining exploration | -75,513735 | 53,473313 | Wemindji | VC25 | <Null> | WJ12/33G |
| WJ/6-054 | 0600-2009-572 | | Mining exploration | -75,1387 | 53,470086 | Wemindji | VC26 | <Null> | WJ08/33G |
| WK/7-003 | 0600-2009-573 | Manquant | Mining exploration | -78,726362 | 50,036258 | Washaw Sibi | 13 | <Null> | WK1/32L |
| WK/7-018 | 0600-2009-574 | | Mining exploration | -77,837075 | 50,901207 | Waskaganish | N05 | <Null> | WK1/32K |
| WK/7-019 | 0600-2009-575 | | Mining exploration | -77,86828 | 50,909711 | Waskaganish | N05 | <Null> | WK2/32K |
| WK/7-020 | 0600-2009-576 | | Mining exploration | -77,887435 | 50,90837 | Waskaganish | N05 | <Null> | WK3/32K |
| WK/7-040 | 0600-2009-577 | | Mining exploration | -79,247689 | 50,914217 | Waskaganish | N10A | <Null> | WK11/32L |
| WP/7-013 | 0600-2009-578 | | Mining exploration | -76,196603 | 54,939172 | Whapmagoostui | GW09 | <Null> | WP2/33K |
| WP/7-027 | 0600-2009-579 | | Mining exploration | -73,260308 | 54,974436 | Whapmagoostui | GW17 | <Null> | WP1/33I |
| WP/7-040 | 0600-2009-580 | | Mining exploration | -76,505619 | 54,723581 | Whapmagoostui | GW07 | <Null> | |
| WS/7-002 | 0600-2009-581 | | Mining exploration | -76,963104 | 49,883202 | Waswanipi | W01 | <Null> | WI31/32F |
| WS/7-021 | 0600-2009-582 | | Mining exploration | -76,34697 | 50,820743 | Waswanipi | W05A | <Null> | WI01/32K |
| WS/7-024 | 0600-2009-583 | | Mining exploration | -76,650337 | 50,799963 | Waswanipi | W05A | <Null> | WI26/32K |
| WS/7-026 | 0600-2009-584 | | Mining exploration | -76,429039 | 50,708465 | Waswanipi | W05C | <Null> | WI20/32K |
| WS/7-028 | 0600-2009-585 | | Mining exploration | -76,448977 | 50,701105 | Waswanipi | W05C | <Null> | WI22/32K |
| WS/7-030 | 0600-2009-586 | | Mining exploration | -76,514362 | 50,795169 | Waswanipi | W05C | <Null> | WI24/32K |

| | | | | | | | | |
|----------|---------------|--------------------|------------|-----------|-----------|------|--------|------------|
| WS/7-038 | 0600-2009-587 | Mining exploration | -76,246675 | 50,680871 | Waswanipi | W05D | CAT II | WI10/32Kne |
| WS/7-051 | 0600-2009-588 | Mining exploration | -77,141056 | 50,635912 | Waswanipi | W06A | <Null> | NA121/32K |
| WS/7-052 | 0600-2009-589 | Mining exploration | -77,053215 | 50,714316 | Waswanipi | W06A | <Null> | NA123/32K |
| WS/7-054 | 0600-2009-590 | Mining exploration | -77,092911 | 50,631291 | Waswanipi | W06A | <Null> | WI02/32Kno |
| WS/7-057 | 0600-2009-591 | Mining exploration | -77,107776 | 50,4996 | Waswanipi | W07 | <Null> | NA120/32K |
| WS/7-068 | 0600-2009-592 | Mining exploration | -76,023208 | 50,468573 | Waswanipi | W10 | CAT II | WI51/32Kse |
| WS/7-074 | 0600-2009-593 | Mining exploration | -76,338976 | 49,938395 | Waswanipi | W11A | CAT II | WI23/32Fne |
| WS/7-076 | 0600-2009-594 | Mining exploration | -76,538987 | 49,817553 | Waswanipi | W11B | CAT II | W21/32Fne |
| WS/7-077 | 0600-2009-595 | Mining exploration | -76,618416 | 49,791624 | Waswanipi | W11B | CAT II | WI22/32Fne |
| WS/7-078 | 0600-2009-596 | Mining exploration | -76,545703 | 49,822885 | Waswanipi | W11B | CAT II | WI25/32Fne |
| WS/7-089 | 0600-2009-597 | Mining exploration | -77,26439 | 49,892463 | Waswanipi | W13 | <Null> | WI17/32Fno |
| WS/7-094 | 0600-2009-598 | Mining exploration | -77,484768 | 49,712779 | Waswanipi | W13A | <Null> | WI03/32Fno |
| WS/7-100 | 0600-2009-599 | Mining exploration | -76,030295 | 49,781688 | Waswanipi | W15 | CAT II | WI11/32Fne |
| WS/7-103 | 0600-2009-600 | Mining exploration | -75,306084 | 49,892581 | Waswanipi | W16 | <Null> | WI02/32Gno |
| WS/7-104 | 0600-2009-601 | Mining exploration | -75,255697 | 49,929712 | Waswanipi | W16 | <Null> | WI03/32Gno |
| WS/7-105 | 0600-2009-602 | Mining exploration | -75,26177 | 49,924974 | Waswanipi | W16 | <Null> | WI04/32Gno |
| WS/7-126 | 0600-2009-603 | Mining exploration | -75,851073 | 49,595274 | Waswanipi | W21 | <Null> | WI12/32Gno |
| WS/7-134 | 0600-2009-604 | Mining exploration | -75,490396 | 50,001785 | Waswanipi | W22 | <Null> | WI01/32Jso |
| WS/7-136 | 0600-2009-605 | Mining exploration | -75,411566 | 49,99147 | Waswanipi | W22 | <Null> | WI03/32Gno |
| WS/7-137 | 0600-2009-606 | Mining exploration | -75,646713 | 49,9026 | Waswanipi | W22 | <Null> | WI04/32Gno |
| WS/7-142 | 0600-2009-607 | Mining exploration | -74,894528 | 49,494605 | Waswanipi | W23A | <Null> | WI01/32Gse |
| WS/7-143 | 0600-2009-608 | Mining exploration | -74,886481 | 49,427858 | Waswanipi | W23A | <Null> | WI02/32Gse |
| WS/7-144 | 0600-2009-609 | Mining exploration | -74,836103 | 49,584358 | Waswanipi | W23A | <Null> | WI03/32Gne |
| WS/7-145 | 0600-2009-610 | Mining exploration | -74,698416 | 49,554084 | Waswanipi | W23A | <Null> | WI04/32Gne |
| WS/7-154 | 0600-2009-611 | Mining exploration | -76,522452 | 49,213043 | Waswanipi | W24B | <Null> | WI07/32Fse |
| WS/7-168 | 0600-2009-612 | Mining exploration | -75,156975 | 49,419799 | Waswanipi | W27 | <Null> | WI02/32Gso |
| WS/7-174 | 0600-2009-613 | Mining exploration | -75,266143 | 49,490622 | Waswanipi | W27 | <Null> | WI20/32Gso |
| WS/7-175 | 0600-2009-614 | Mining exploration | -75,36644 | 49,524115 | Waswanipi | W27 | <Null> | WI22/32Gno |
| WS/7-176 | 0600-2009-615 | Mining exploration | -75,296244 | 49,492625 | Waswanipi | W27 | <Null> | WI2/32Gso |
| WS/7-177 | 0600-2009-616 | Mining exploration | -75,306097 | 49,483145 | Waswanipi | W27 | <Null> | WI24/32Gso |
| WS/7-178 | 0600-2009-617 | Mining exploration | -75,318069 | 49,473658 | Waswanipi | W27 | <Null> | WI25/32Gso |
| WS/7-179 | 0600-2009-618 | Mining exploration | -75,24592 | 49,481444 | Waswanipi | W27 | <Null> | WI26/32Gso |
| WS/7-183 | 0600-2009-238 | Mining exploration | -76,169608 | 49,496031 | Waswanipi | W24A | <Null> | <Null> |



Site Characterization Report

Submitted By: amasty_cng **Submitted Time:** July 20, 2021 1:46 PM

| Site Information | |
|---|---|
| <p>Site Number: MI/6-084</p> <p>Community: Mistissini</p> <p>Inventory by: Adario Masty</p> <p>Date and Time: July 3, 2021 3:06 PM</p> <p>Distance from surface water (m): 20</p> <p>Soil :</p> <p>Drainage :</p> <p>Site size (hectares): 1.2238867653212389</p> | <p>Site Location:</p>  <p style="font-size: small; text-align: center;">Maxar Cree Nation Government Esri Community ... Powered b</p> |

| Drums | | | | | |
|---|-------------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: 8 | | | | | |
| Content: Jet Fuel Name of other: | | | | | |
| Gas | Jet Fuel | Diesel | Oil | Grease | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: 8 | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): Less than 50 m | | | | | |
| Photo Drums: | | | | | |



| Reservoirs | | | | |
|--|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: | | | | |
| Content: Name of other: | | | | |
| Gas | Jet Fuel | Diesel | Oil | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): | | | | |
| Photo Reservoirs: | | | | |

| Propane Tanks | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Propane tanks: | | |

| Batteries | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Batteries: | | |

| Transformers | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Transformers: | | |



| | |
|---------------------------------|--------------------------------|
| Infrastructures | |
| Nb Cabin: Condition: | Nb Tent: Condition: |
| Photo Infrastructures: | |

| | | | | | | | |
|--|---------------------------|-------------------------|---------------------------------|---------------------------|--------------------------|---------------------------------|-------------------------|
| Machinery and Equipment | | | | | | | |
| Machinery: Name of other: | | | | | | | |
| Nb of Bulldoze r: | Nb of Tractor: | Nb of Truck: | Nb of Conveyo r: | Nb of Crusher: | Nb of Muskeg: | Nb of Generat or | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Machinery: | | | | | | | |

| | | | | | | | |
|---|------------------------|---------------------------|-------------------------|------------------------|--------------------------|--------------------------------|-------------------------|
| Solid Waste and Dry Material (m3 = cubic meters) | | | | | | | |
| Material: Name of Other: | | | | | | | |
| Nb of Core Samplin g: | Nb of Wood: | Nb of Plastic: | Nb of Metal: | Nb of Rods: | Nb of Cables: | Nb of Garbage : | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Waste: | | | | | | | |

| |
|----------------------------------|
| Evidence of Contamination |
|----------------------------------|



| | |
|--|-----------------------------------|
| Yes/No: No | Contamination Description: |
| Other Information : Couldn't land but tally man confirmed he recently inspected and drums were full. Can easily be cleaned once landing pad is made. | |
| Photo Contamination: | |





Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 4, 2021 7:57 PM

| Site Information | |
|---|------------------------------|
| <p>Site Number: MI/6-087</p> <p>Community: Mistissini</p> <p>Inventory by: Adario Masty</p> <p>Date and Time: July 3, 2021 9:49 AM</p> <p>Distance from surface water (m): 30</p> <p>Soil :</p> <p>Drainage :</p> <p>Site size (hectares): 1.2250259532352048</p> | <p>Site Location:</p> |

| Drums | | | | | |
|---|-----------------------|--------------------------|-----------------------|-----------------------|-----------------------|
| Nb total: 10 | | | | | |
| Content: Diesel Name of other: | | | | | |
| Gas | Jet Fuel | Diesel | Oil | Grease | Other |
| Nb of empty: | Nb of empty: | Nb of empty: 8 | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: 2 | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): Less than 50 m | | | | | |
| Photo Drums: | | | | | |



| Reservoirs | | | | |
|--|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: | | | | |
| Content: Name of other: | | | | |
| Gas | Jet Fuel | Diesel | Oil | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): | | | | |
| Photo Reservoirs: | | | | |

| Propane Tanks | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Propane tanks: | | |

| Batteries | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Batteries: | | |

| Transformers | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Transformers: | | |



| | |
|---------------------------------|--------------------------------|
| Infrastructures | |
| Nb Cabin: Condition: | Nb Tent: Condition: |
| Photo Infrastructures: | |

| | | | | | | | |
|--|---------------------------|-------------------------|---------------------------------|---------------------------|--------------------------|---------------------------------|-------------------------|
| Machinery and Equipment | | | | | | | |
| Machinery: Name of other: | | | | | | | |
| Nb of Bulldoze r: | Nb of Tractor: | Nb of Truck: | Nb of Conveyo r: | Nb of Crusher: | Nb of Muskeg: | Nb of Generat or | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Machinery: | | | | | | | |

| | | | | | | | |
|---|------------------------|---------------------------|-------------------------|------------------------|--------------------------|--------------------------------|-------------------------|
| Solid Waste and Dry Material (m3 = cubic meters) | | | | | | | |
| Material: Metal Name of Other: | | | | | | | |
| Nb of Core Samplin g: | Nb of Wood: | Nb of Plastic: | Nb of Metal: | Nb of Rods: | Nb of Cables: | Nb of Garbage : | Nb of Other: |
| Distance from a sensitive area (m): Less than 50 m | | | | | | | |
| Photo Waste: | | | | | | | |

| |
|----------------------------------|
| Evidence of Contamination |
|----------------------------------|



| | |
|---|-----------------------------------|
| Yes/No: No | Contamination Description: |
| Other Information : Camp reclaimed by nature, old stove pipes and other metal pieces. Very rusty. Helicopter can land on the point. Could be cleaned in 1 day by sling with 2 workers .s\ | |
| Photo Contamination: | |









53-54






53-54





Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 19, 2021 6:09 PM

| Site Information | |
|--|---|
| <p>Site Number: MI/6-090</p> <p>Community: Mistissini</p> <p>Inventory by: Adario Masty</p> <p>Date and Time: July 3, 2021 1:25 PM</p> <p>Distance from surface water (m): 1</p> <p>Soil :</p> <p>Drainage :</p> <p>Site size (hectares): 0.1379474021019611</p> | <p>Site Location:</p>  <p>Maxar Cree Nation Government Esri Community ... Powered b</p> |

| Drums | | | | | |
|---|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: 11 | | | | | |
| Content: Name of other: | | | | | |
| Gas | Jet Fuel | Diesel | Oil | Grease | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): Less than 50 m | | | | | |
| Photo Drums: | | | | | |



| Reservoirs | | | | |
|--|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: | | | | |
| Content: Name of other: | | | | |
| Gas | Jet Fuel | Diesel | Oil | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): | | | | |
| Photo Reservoirs: | | | | |

| Propane Tanks | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Propane tanks: | | |

| Batteries | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Batteries: | | |

| Transformers | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Transformers: | | |



| | |
|---------------------------------|--------------------------------|
| Infrastructures | |
| Nb Cabin: Condition: | Nb Tent: Condition: |
| Photo Infrastructures: | |

| | | | | | | | |
|--|---------------------------|-------------------------|---------------------------------|---------------------------|--------------------------|---------------------------------|-------------------------|
| Machinery and Equipment | | | | | | | |
| Machinery: Name of other: | | | | | | | |
| Nb of Bulldoze r: | Nb of Tractor: | Nb of Truck: | Nb of Conveyo r: | Nb of Crusher: | Nb of Muskeg: | Nb of Generat or | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Machinery: | | | | | | | |

| | | | | | | | |
|---|------------------------|---------------------------|-------------------------|------------------------|--------------------------|--------------------------------|-------------------------|
| Solid Waste and Dry Material (m3 = cubic meters) | | | | | | | |
| Material: Name of Other: | | | | | | | |
| Nb of Core Samplin g: | Nb of Wood: | Nb of Plastic: | Nb of Metal: | Nb of Rods: | Nb of Cables: | Nb of Garbage : | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Waste: | | | | | | | |


| |
|----------------------------------|
| Evidence of Contamination |
|----------------------------------|



| | |
|---|-----------------------------------|
| Yes/No: No | Contamination Description: |
| Other Information : Couldn't land, to many trees . Need to cut a pad or go by float plane . Need to go back to check if drums are empty | |
| Photo Contamination: | |

| |
|--|
| Other Photo:  |
|--|







Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 1, 2021 10:46 PM

| Site Information | |
|--|---|
| <p>Site Number: MI/6-106</p> <p>Community: Mistissini</p> <p>Inventory by: Adario Masty</p> <p>Date and Time: July 1, 2021 10:41 PM</p> <p>Distance from surface water (m): 10</p> <p>Soil :</p> <p>Drainage :</p> <p>Site size (hectares): 0.1924066606789832</p> | <p>Site Location:</p>  <p>Maxar Cree Nation Government Esri Community ... Powered b</p> |

| Drums | | | | | |
|---|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: 2 | | | | | |
| Content: Other Name of other: | | | | | |
| Gas | Jet Fuel | Diesel | Oil | Grease | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): Less than 50 m | | | | | |
| Photo Drums: | | | | | |



| Reservoirs | | | | |
|--|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: | | | | |
| Content: Name of other: | | | | |
| Gas | Jet Fuel | Diesel | Oil | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): | | | | |
| Photo Reservoirs: | | | | |

| Propane Tanks | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Propane tanks: | | |

| Batteries | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Batteries: | | |

| Transformers | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Transformers: | | |



| | |
|---------------------------------|--------------------------------|
| Infrastructures | |
| Nb Cabin: Condition: | Nb Tent: Condition: |
| Photo Infrastructures: | |

| | | | | | | | |
|--|---------------------------|-------------------------|---------------------------------|---------------------------|--------------------------|---------------------------------|-------------------------|
| Machinery and Equipment | | | | | | | |
| Machinery: Name of other: | | | | | | | |
| Nb of Bulldoze r: | Nb of Tractor: | Nb of Truck: | Nb of Conveyo r: | Nb of Crusher: | Nb of Muskeg: | Nb of Generat or | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Machinery: | | | | | | | |

| | | | | | | | |
|---|------------------------|---------------------------|-------------------------|------------------------|--------------------------|--------------------------------|-------------------------|
| Solid Waste and Dry Material (m3 = cubic meters) | | | | | | | |
| Material: Name of Other: | | | | | | | |
| Nb of Core Samplin g: | Nb of Wood: | Nb of Plastic: | Nb of Metal: | Nb of Rods: | Nb of Cables: | Nb of Garbage : | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Waste: | | | | | | | |

| |
|----------------------------------|
| Evidence of Contamination |
|----------------------------------|



| | |
|---|-----------------------------------|
| Yes/No: No | Contamination Description: |
| Other Information : 2 old drums on site , unsafe to land , took pictures. Tall man says drums are empty | |
| Photo Contamination: | |





Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 1, 2021 10:28 PM

| Site Information | |
|---|---|
| <p>Site Number: MI/6-113</p> <p>Community: Mistissini</p> <p>Inventory by: Adario Masty</p> <p>Date and Time: July 1, 2021 11:32 AM</p> <p>Distance from surface water (m): 5</p> <p>Soil :</p> <p>Drainage :</p> <p>Site size (hectares): 1.1660639462487565</p> | <p>Site Location:</p>  <p>Maxar Cree Nation Government Esri Community ... Powered b</p> |

| Drums | | | | | |
|---|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: 8 | | | | | |
| Content: Name of other: | | | | | |
| Gas | Jet Fuel | Diesel | Oil | Grease | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): Less than 50 m | | | | | |
| Photo Drums: | | | | | |



| Reservoirs | | | | |
|--|-----------------------|-----------------------|-----------------------|-----------------------|
| Nb total: | | | | |
| Content: Name of other: | | | | |
| Gas | Jet Fuel | Diesel | Oil | Other |
| Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: | Nb of empty: |
| Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: | Nb of partial: |
| Nb of full: | Nb of full: | Nb of full: | Nb of full: | Nb of full: |
| Distance from a sensitive area (m): | | | | |
| Photo Reservoirs: | | | | |

| Propane Tanks | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Propane tanks: | | |

| Batteries | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Batteries: | | |

| Transformers | | |
|--|---------------------------|--------------------------|
| Nb total: | | |
| Nb Good condition: | Nb Fair condition: | Nb Bad Condition: |
| Distance from a sensitive area (m): | | |
| Photo Transformers: | | |



| | |
|---------------------------------|--------------------------------|
| Infrastructures | |
| Nb Cabin: Condition: | Nb Tent: Condition: |
| Photo Infrastructures: | |


| | | | | | | | |
|--|---------------------------|-------------------------|---------------------------------|---------------------------|--------------------------|---------------------------------|-------------------------|
| Machinery and Equipment | | | | | | | |
| Machinery: Name of other: | | | | | | | |
| Nb of Bulldoze r: | Nb of Tractor: | Nb of Truck: | Nb of Conveyo r: | Nb of Crusher: | Nb of Muskeg: | Nb of Generat or | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Machinery: | | | | | | | |

| | | | | | | | |
|---|------------------------|---------------------------|-------------------------|------------------------|--------------------------|--------------------------------|-------------------------|
| Solid Waste and Dry Material (m3 = cubic meters) | | | | | | | |
| Material: Name of Other: | | | | | | | |
| Nb of Core Samplin g: | Nb of Wood: | Nb of Plastic: | Nb of Metal: | Nb of Rods: | Nb of Cables: | Nb of Garbage : | Nb of Other: |
| Distance from a sensitive area (m): | | | | | | | |
| Photo Waste: | | | | | | | |

| |
|----------------------------------|
| Evidence of Contamination |
|----------------------------------|



| | |
|--|-----------------------------------|
| Yes/No: No | Contamination Description: |
| Other Information : 5 drums in one spot in fair condition. 3 other drums spread out along shore. | |
| Photo Contamination: | |









Sites deemed active but have waste or debris on trapline M16

Site# MI/6-062

Region

Mistissini

Nb total of Drums

1

Nb total of Batteries

5

Drums

Content

- **Other**

Other

Nb of empty

1

Distance from a sensitive area (m)

Less than 50 m

Batteries

Batteries condition

- **Bad**

Nb bad Batteries

5

Distance from a sensitive area (m)

Less than 50 m

Infrastructures

Nb Cabin

1

Cabin Condition

- **Bad**

Machinery and Equipment

Machinery and Equipment

- **Other**

Solid Waste and Dry Material

Solid Waste and Dry Material

- **Core Sampling**
- **Rods**
- **Debris and domestic garbage**
- **Plastic**
- **Metal**
- **Cables**







Site Number

MI/6-069

Nb total of Drums

16

Drums

Content

- **Diesel**



Site Number

MI/21-326

Nb total of Drums

10 empty

Nb total of Propane tanks

3

1 fridge , 1 hot water tank,1 washing machine,1 water pump. Belonged to a company named Dios about 16 years ago according to tallyman.





Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 19, 2021, 4:22:01 p.m.

Visit Information

Site Number

MI/6-091

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 3, 2021, 1:07:00 p.m.

Site Information

Site Location

Area: 6.9 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Nothing on site,flew by area 3 times

mine_site_pts_GlobalID

84d90b5c-fad8-4f2c-a2c1-8c34b3c7f8ff

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 10:59:14 p.m.

Visit Information

Site Number

MI/6-103

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:57:00 p.m.


Site Information

Distance from surface water (m)

20

Site Location

Area: 1.11 Hectares



Maxar Powered by Esri

Infrastructures

Nb Cabin

1

Evidence of Contamination

Contamination

No

Other informations

Old cabin almost all reclaimed by nature. 1 drum was also located about 1 km west of cabin.

mine_site_pts_GlobalID



85fe2179-353d-4c3e-aa05-bfe06c5e0d1c

Attachments:



Ada

.jpg



Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 11:06:40 p.m.

Visit Information

Site Number

MI/6-104

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 1:08:00 p.m.

Site Information

Site Location

Area: 1.29 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Flew sector , nothing visible

mine_site_pts_GlobalID

f5ee410d-26ad-46c4-861f-0739380fa557

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 10:28:13 p.m.

Visit Information

Site Number

MI/6-107

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 11:39:00 a.m.

Site Information

Distance from surface water (m)

20

Site Location

Area: 8,656.94 Sq meters



Maxar

Powered by Esri

Presence of Drums, Tanks, Batteries or Transformer

Nb total of Drums

5

Drums

Distance from a sensitive area (m)

Less than 50 m

Solid Waste and Dry Material

Solid Waste and Dry Material

- **Core Sampling**
- **Metal**

Distance from a sensitive area (m)

Less than 50 m

Evidence of Contamination

Contamination

No

Other informations

5 drums . Tally man checked them before and were empty. Lots of core samples refer tp pictures of core sample racks, lots of small metal cans which looks like napta cans used for cooking and lamps.refer to pictures

mine_site_pts_GlobalID

5f27b5e3-d27f-4ad5-b00e-413b762f053e

Attachments:



Adandoned_Mine_site_p_image-20210701-222405.jpg





IMG_0334.JPG



IMG_0339.JPG



IMG_0336.JPG

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 5:31:00 p.m.

Visit Information

Site Number

MI/6-108

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:30:00 p.m.

Site Information

Distance from surface water (m)

1

Site Location

Area: 9,507.18 Sq meters



Maxar

Powered by Esri

Presence of Drums, Tanks, Batteries or Transformer

Nb total of Drums

21

Drums

Content

- **Other**

Other

Nb of empty

21

Distance from a sensitive area (m)

Less than 50 m

Solid Waste and Dry Material

Solid Waste and Dry Material

- **Other**

Material volume (m3)

Distance from a sensitive area (m)

Less than 50 m

Evidence of Contamination

Contamination

No

Other informations

Claude has indicated drums are empty ,more info to be entered, possible cleanup tomorrow with helicopter. Cleaned.

mine_site_pts_GlobalID



8db21bbb-2054-4128-875c-838318b36567


Attachments:



Ada

.jpg





Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 9:09:56 p.m.

Visit Information

Site Number

MI/6-109

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:43:00 p.m.

Site Information

Site Location

Area: 1.96 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Nothing on site,flew by 2 passes

mine_site_pts_GlobalID

72f5baca-91af-47f3-bf43-2eb1e419da20

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 9:29:16 p.m.

Visit Information

Site Number

MI/6-110

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:00:00 p.m.

Site Information

Site Location

Area: 6.78 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Nothing on site , several flyby. Cleaned or no longer on site

mine_site_pts_GlobalID

db7a821d-b85f-4391-8831-a21ddcaac9ed



Photo 1



Photo 2