

PAR COURRIEL

Le 3 octobre 2025

DEMANDEUR

N/Réf. : 202509-70

Objet : Demande d'accès à l'information

Monsieur,

Nous faisons suite à votre demande d'accès à l'information, reçue le 18 septembre 2025.

Vous trouverez ci-jointe une copie des documents détenus par le ministère des Ressources naturelles et des Forêts, relativement à cette demande.

Sur réception de ces documents, vous remarquerez que nous avons soustrait certains renseignements, comme le permet l'article 14 de la Loi sur l'accès aux documents des organismes publics et sur la protection des renseignements personnels (RLRQ, chapitre A-2.1), ci-après Loi sur l'accès. En effet, nous avons masqué les renseignements confidentiels au sens des articles 53 et 54 de cette loi.

Par ailleurs, nous vous informons que les sites miniers mentionnés dans la présente demande - à savoir les 192 sites d'exploration, le site Icon Sullivan ainsi que la sablière 33F13-3 - relèvent de la responsabilité de l'État. La gestion et le suivi de ces sites sont assurés par la Direction de la restauration des sites miniers et du passif environnemental.

Nous souhaitons également préciser que les sites miniers abandonnés, (intégrant aussi les sites d'exploration minières abandonnés) sous la responsabilité du ministère des Ressources naturelles et des Forêts sont identifiés sur la [carte interactive des sites contaminés sous la responsabilité de l'État](#). Cette carte, qui comprend également les sites relevant d'autres ministères et organismes, est mise à jour sur une base annuelle.

Enfin, veuillez noter que certains documents visés par votre demande d'accès à l'information font l'objet d'une publication ou d'une diffusion au sens de l'article 13 de la Loi sur l'accès aux documents des organismes publics et sur la protection des renseignements personnels (RLRQ, chapitre A-2.1). Vous les trouverez dans le

Site_nm	Étiquette PTSC	Rapport d'inventaire	Site_type	x_coord	y_coord	COMUNITY	TRAPLINE	CAT	Nom de la Consultation
CH/6-050	0600-2009-417		Mining exploration	-73,796714	53,929084	Chisasibi	FG21/CH21	<Null>	CH1/33H
CH/6-052	0600-2009-418		Mining exploration	-73,699912	53,929566	Chisasibi	FG21/CH21	<Null>	CH3/33H
CH/6-062	0600-2009-419		Mining exploration	-71,241312	54,61933	Chisasibi	FG31/CH31	<Null>	CH2/23L
CH/6-073	0600-2009-420		Mining exploration	-77,753986	53,499334	Chisasibi	VC04/CH36	<Null>	CH25/33F
CH/6-080	0600-2009-421		Mining exploration	-77,262594	53,408021	Chisasibi	VC06/CH38	<Null>	CH02/33F
CH/6-082	0600-2009-422		Mining exploration	-77,570807	53,372321	Chisasibi	VC06/CH38	<Null>	CH04/33F
CH/6-083	0600-2009-423		Mining exploration	-77,478433	53,370542	Chisasibi	VC06/CH38	<Null>	CH06/33F
CH/6-085	0600-2009-424		Mining exploration	-77,41366	53,39054	Chisasibi	VC06/CH38	<Null>	CH08/33F
CH/6-086	0600-2009-425		Mining exploration	-77,647992	53,352792	Chisasibi	VC06/CH38	CAT II	CH09/33F
CH/6-087	0600-2009-426		Mining exploration	-77,603352	53,337178	Chisasibi	VC06/CH38	<Null>	CH10/33F
CH/6-090	0600-2009-427		Mining exploration	-78,053449	53,270689	Chisasibi	VC06/CH38	CAT II	CH01/33E
ET/6-002	0600-2009-428		Mining exploration	-77,503491	52,44632	Eastmain	VC33	<Null>	E09/33C
ET/6-003	0600-2009-429		Mining exploration	-77,664534	52,359688	Eastmain	VC33	CAT II	E10/33C
ET/6-004	0600-2009-430		Mining exploration	-77,705701	52,361458	Eastmain	VC33	CAT II	E11/33C
ET/6-007	0600-2009-431		Mining exploration	-76,492339	52,483323	Eastmain	VC35	<Null>	E19/33C
ET/6-009	0600-2009-432		Mining exploration	-76,593829	52,213467	Eastmain	VC35	<Null>	E01/33C
ET/6-014	0600-2009-433		Mining exploration	-75,895311	52,211917	Eastmain	VC37	<Null>	E01/33B
ET/6-015	0600-2009-434		Mining exploration	-75,723843	52,192743	Eastmain	VC37	<Null>	E02/33B
ET/6-016	0600-2009-435		Mining exploration	-75,66303	52,185639	Eastmain	VC37	<Null>	E03/33B
ET/6-019	0600-2009-436		Mining exploration	-76,366324	52,247289	Eastmain	VC35	<Null>	E04/33C
ET/6-020	0600-2009-437		Mining exploration	-76,389833	52,213071	Eastmain	RE01	<Null>	E05/33C
ET/6-021	0600-2009-438		Mining exploration	-76,249884	52,209607	Eastmain	RE01	<Null>	E06/33C
ET/6-024	0600-2009-439		Mining exploration	-77,095957	52,320529	Eastmain	VC33	<Null>	E13/33C
MI/21-327	0600-2009-440	MI6-062_MI6-069_MI21-326.docx	Mining exploration	-72,198826	51,882939				
MI/6-017	0600-2009-441		Mining exploration	-71,227221	53,616994	Mistissini	M01	<Null>	MS25/23E
MI/6-026	0600-2009-442		Mining exploration	-70,524656	53,249547	Mistissini	M07	<Null>	MS16/23E
MI/6-034	0600-2009-443		Mining exploration	-74,339487	52,787928	Mistissini	M08	<Null>	MS04/33B
MI/6-042	0600-2009-444		Mining exploration	-71,932635	52,900551	Mistissini	M11	<Null>	MS01/23D
MI/6-045	0600-2009-445		Mining exploration	-72,133001	52,536125				
MI/6-046	0600-2009-446		Mining exploration	-72,261654	52,641716	Mistissini	M11	<Null>	MS04/33A
MI/6-049	0600-2009-448		Mining exploration	-71,279557	52,673655	Mistissini	M12	<Null>	MS35/23D
MI/6-062	0600-2009-450		Mining exploration	-72,099168	52,343435	Mistissini	M16	<Null>	MS20/33A
MI/6-066	0600-2009-451		Mining exploration	-72,135768	52,45577	Mistissini	M16	<Null>	MS24/33A
MI/6-067	0600-2009-452	MI6-062_MI6-069_MI21-326.docx	Mining exploration	-72,122033	52,454881	Mistissini	M16	<Null>	MS25/33A
MI/6-068	0600-2009-453		Mining exploration	-72,132659	52,151526	Mistissini	M16	<Null>	MS26/33A
MI/6-069	0600-2009-454		Mining exploration	-71,802475	52,583301	Mistissini	M16	<Null>	MS45/23D
MI/6-070	0600-2009-455		Mining exploration	-71,947478	52,353595	Mistissini	M16	<Null>	MS46/23D
MI/6-071	0600-2009-456		Mining exploration	-71,838185	52,643327	Mistissini	M16	<Null>	MS47/23D
MI/6-074	0600-2009-457		Mining exploration	-71,904142	52,500479	Mistissini	M16	<Null>	MS50/23D
MI/6-075	0600-2009-458		Mining exploration	-71,862198	52,225492	Mistissini	M17	<Null>	MS30/23D
MI/6-076	0600-2009-459		Mining exploration	-71,861485	52,147133	Mistissini	M17	<Null>	MS31/23D
MI/6-077	0600-2009-460		Mining exploration	-71,744848	52,067581	Mistissini	M17	<Null>	MS32/23D
MI/6-079	0600-2009-461		Mining exploration	-71,823187	51,92158	Mistissini	M17	<Null>	MS07/22M
MI/6-084	0600-2009-462	Mistissini MI6-084.pdf	Mining exploration	-71,409346	52,076566	Mistissini	M17B	<Null>	MS06/23D
MI/6-085	0600-2009-463	Abandoned Mine sites_MI6-087.pdf	Mining exploration	-71,056608	52,278749				
MI/6-087	0600-2009-464		Mining exploration	-70,903896	52,110132	Mistissini	M17B	<Null>	MS09/23D
MI/6-090	0600-2009-465		Mining exploration	-71,11101	52,311566	Mistissini	M17B	<Null>	MS12/23D
MI/6-091	0600-2009-466	Mistissini MI6-091.pdf	Mining exploration	-70,95365	52,418069	Mistissini	M17B	<Null>	MS13/23D
MI/6-101	0600-2009-467	Mistissini MI6-103.pdf	Mining exploration	-71,314277	52,057762				
MI/6-103	0600-2009-468		Mining exploration	-71,622961	51,705982	Mistissini	M17C	<Null>	MS01/22M
MI/6-104	0600-2009-469		Mining exploration	-71,714257	51,707201	Mistissini	M17C	<Null>	MS02/22M

MI/6-106	0600-2009-470	Abandoned Mine sites_MI6-106.pdf	Mining exploration	-71,912527	51,793459	Mistissini	M17C	<Null>	MS04/22M
MI/6-107	0600-2009-471	Mistissini MI6-107.pdf	Mining exploration	-71,992299	51,784997	Mistissini	M17C	<Null>	MS05/22M
MI/6-108	0600-2009-472	Mistissini MI6-108.pdf	Mining exploration	-71,812881	51,886972	Mistissini	M17C	<Null>	MS06/22M
MI/6-109	0600-2009-473	Mistissini MI6-109.pdf	Mining exploration	-71,821115	51,865426	Mistissini	M17C	<Null>	MS10/22M
MI/6-110	0600-2009-474	Mistissini MI6-110.pdf	Mining exploration	-71,971925	51,845106	Mistissini	M17C	<Null>	MS11/22M
MI/6-113	0600-2009-475	Abandoned Mine sites_MI6-113.pdf	Mining exploration	-72,024622	51,803648	Mistissini	M17C	<Null>	MS07/32P
MI/6-115	0600-2009-476		Mining exploration	-72,028578	51,946132	Mistissini	M17C	<Null>	MS09/32P
MI/6-120	0600-2009-477		Mining exploration	-72,676696	52,281077	Mistissini	M23	<Null>	MS05/33A
MI/6-122	0600-2009-479		Mining exploration	-72,78045	52,325415	Mistissini	M23	<Null>	MS07/33A
MI/6-129	0600-2009-480		Mining exploration	-72,758631	51,459914	Mistissini	M29	CAT II	MS11/32P
MI/6-130	0600-2009-481		Mining exploration	-72,740183	51,491176	Mistissini	M29A	CAT II	MS12/32P
MI/6-132	0600-2009-482		Mining exploration	-72,618032	51,464406	Mistissini	M29	CAT II	MS14/32P
MI/6-147	0600-2009-483		Mining exploration	-73,815408	51,021246	Mistissini	M35	CAT II	MS31/32P
MI/6-161	0600-2009-484		Mining exploration	-72,840366	51,143383	Mistissini	M42	<Null>	MS01/32P
MI/6-164	0600-2009-485		Mining exploration	-72,652616	51,236675				
MI/6-166	0600-2009-486		Mining exploration	-73,089985	51,002727	Mistissini	M42A	<Null>	MS25/32P
MI/6-171	0600-2009-487		Mining exploration	-73,234988	50,913050				
MI/6-172	0600-2009-488		Mining exploration	-73,046527	50,973676				
MI/6-173	0600-2009-489		Mining exploration	-72,827065	51,095879	Mistissini	M42	<Null>	MS51/32P
MI/6-174	0600-2009-490		Mining exploration	-72,727251	51,135564	Mistissini	M42	<Null>	MS52/32P
MI/6-180	0600-2009-491		Mining exploration	-75,382369	50,587424	Mistissini	M47	<Null>	MS25/32J
MI/6-182	0600-2009-492		Mining exploration	-75,531924	50,414122	Mistissini	M47A	<Null>	MS11/32J
MI/6-189	0600-2009-493		Mining exploration	-73,833852	50,185077	Mistissini	M51	<Null>	MS10/32I
MI/6-191	0600-2009-494		Mining exploration	-73,775198	50,268503	Mistissini	M51	CAT II	MS12/32I
MI/6-199	0600-2009-496		Mining exploration	-73,977016	50,157197	Mistissini	M56	<Null>	MS02/32I
MI/7-205	0600-2009-497		Mining exploration	-74,507942	52,10827	Mistissini	M14	<Null>	MI51/33B
MI/7-208	0600-2009-498		Mining exploration	-74,971289	52,403371	Mistissini	M14A	<Null>	MI33/33B
MI/7-223	0600-2009-499		Mining exploration	-71,490337	52,258071	Mistissini	M17	<Null>	MI103/23D
MI/7-225	0600-2009-500		Mining exploration	-71,252401	52,359454	Mistissini	M17A	<Null>	MI104/23D
MI/7-227	0600-2009-501		Mining exploration	-71,204305	52,151675	Mistissini	M17B	<Null>	MI107/23D
MI/7-229	0600-2009-502		Mining exploration	-72,092166	51,956452	Mistissini	M17C	<Null>	MI103/32P
MI/7-236	0600-2009-503		Mining exploration	-73,929735	51,931025	Mistissini	M22	<Null>	MI151/32P
MI/7-237	0600-2009-504		Mining exploration	-73,841159	51,810368	Mistissini	M22	CAT II	MI152/32P
MI/7-239	0600-2009-505		Mining exploration	-75,1837	51,818119	Mistissini	M25	<Null>	MI120/32O
MI/7-251	0600-2009-506		Mining exploration	-73,129667	51,682964	Mistissini	M28	CAT II	MI112/32P
MI/7-255	0600-2009-508		Mining exploration	-73,463423	51,366501	Mistissini	M28A	CAT II	MI116/32P
MI/7-257	0600-2009-509		Mining exploration	-73,295472	51,474087	Mistissini	M28A	CAT II	MI118/32P
MI/7-265	0600-2009-510		Mining exploration	-72,685278	51,213377	Mistissini	M36	<Null>	MI100/32P
MI/7-276B	0600-2009-512		Mining exploration	-74,745204	50,729538	Mistissini	M40	<Null>	MI45/32J
MI/7-278	0600-2009-513		Mining exploration	-74,566169	50,869089	Mistissini	M40	<Null>	MI47/32J
MI/7-279	0600-2009-514		Mining exploration	-74,87761	50,736703	Mistissini	M40	<Null>	MI48/32J
MI/7-281	0600-2009-515		Mining exploration	-74,454455	50,682024	Mistissini	M41	<Null>	MI50/32J
MI/7-293	0600-2009-517		Mining exploration	-73,702815	50,342848	Mistissini	M51B	CAT II	MI105/32I
MI/7-295	0600-2009-518		Mining exploration	-75,510713	52,056678	Mistissini	M18	<Null>	MI01/Map M-18
MI/7-304	0600-2009-523		Mining exploration	-72,652371	51,780694	Mistissini	M29A	CAT II	MI02/32Pne
MI/7-305	0600-2009-524		Mining exploration	-72,484932	51,7516	Mistissini	M29A	CAT II	MI03/32Pne
MI/7-306	0600-2009-525		Mining exploration	-72,763888	51,523903	Mistissini	M29A	CAT II	MI04/32Pne
MI/7-307	0600-2009-526		Mining exploration	-72,642238	51,570768	Mistissini	M29A	CAT II	MI05/32Pne
MI/7-308	0600-2009-527		Mining exploration	-72,782903	51,480711	Mistissini	M29A	CAT II	MI06/General location
MI/7-309	0600-2009-528		Mining exploration	-72,755245	51,67215	Mistissini	M29A	CAT II	MI07/32Pne
MI/7-311	0600-2009-529		Mining exploration	-72,697244	51,535511	Mistissini	M29A	CAT II	MI09/32Pne
MI/7-312	0600-2009-530		Mining exploration	-72,671431	51,52026	Mistissini	M29A	CAT II	MI10/32Pne
MI/7-314	0600-2009-531		Mining exploration	-72,235152	51,505796	Mistissini	M30	<Null>	MI03/Map M-30
MI/7-316	0600-2009-532		Mining exploration	-74,634448	51,107993	Mistissini	M39A	<Null>	MI02/32Ose

MOB/7-001	0600-2009-533	2 photos	Mining exploration	-73,993456	50,002624	Ouje-Bougoumou	O57/M57	<Null>	MI100/32I
MOB/7-002	0600-2009-534		Mining exploration	-73,975489	50,035378	Ouje-Bougoumou	O57/M57	<Null>	MI101/32I
MOB/7-003	0600-2009-535		Mining exploration	-73,980196	49,974761	Ouje-Bougoumou	O57/M57	<Null>	MI102/32I
MOB/7-004	0600-2009-536		Mining exploration	-74,025305	49,964104	Ouje-Bougoumou	O57/M57	<Null>	MI103/32I
MOB/7-005	0600-2009-537		Mining exploration	-74,016483	49,920152	Ouje-Bougoumou	O57/M57	<Null>	MI104/32I
MOB/7-006	0600-2009-538		Mining exploration	-74,04565	49,918008	Ouje-Bougoumou	O57/M57	<Null>	MI104/32I
MOB/7-007	0600-2009-539		Mining exploration	-74,022271	49,908262	Ouje-Bougoumou	O57/M57	<Null>	MI105/32I
MOB/7-017	0600-2009-540		Mining exploration	-74,237177	49,938231	Ouje-Bougoumou	O57/M57	<Null>	MI110/32I
MOB/7-019	0600-2009-541		Mining exploration	-74,100383	49,98262	Ouje-Bougoumou	O57/M57	<Null>	MI112/32I
MOB/7-025	0600-2009-542		Mining exploration	-74,106583	49,910266	Ouje-Bougoumou	O57/M57	<Null>	MI17/m57a
MOB/7-026	0600-2009-543		Mining exploration	-73,888662	49,914356	Ouje-Bougoumou	O57/M57	<Null>	MI09/m57a
MOB/7-029	0600-2009-544		Mining exploration	-74,181945	49,927836	Ouje-Bougoumou	O57/M57	<Null>	MI16/m57a
MOB/7-031	0600-2009-545		Mining exploration	-73,938532	50,08359	Ouje-Bougoumou	O57/M57	<Null>	OJ1/o57a
MOB/7-033	0600-2009-546		Mining exploration	-73,98967	49,830643	Ouje-Bougoumou	O57/M57	<Null>	OJ4/o57a
NA/6-006	0600-2009-547		Mining exploration	-77,199479	50,772863	Nemaska	N19	<Null>	NA128/32K
NA/6-013	0600-2009-548		Mining exploration	-77,37445	50,615966	Nemaska	N20	<Null>	NA112/32K
NA/6-014	0600-2009-549		Mining exploration	-77,566914	50,648445	Nemaska	N20	<Null>	NA1/32K
NA/6-015	0600-2009-550		Mining exploration	-77,279591	50,552906	Nemaska	N20	<Null>	NA111/32K
NA/6-016	0600-2009-551		Mining exploration	-77,216243	50,59413	Nemaska	N20	<Null>	NA110/32K
NA/6-027	0600-2009-552		Mining exploration	-77,321219	50,924429	Nemaska	N21	<Null>	NA131/32K
NA/6-032	0600-2009-553		Mining exploration	-77,48361	51,224845	Nemaska	N23	<Null>	NA26/32N
NA/6-041	0600-2009-554		Mining exploration	-76,984672	51,315748	Nemaska	N23	<Null>	NA111/32N
NA/6-070	0600-2009-555		Mining exploration	-76,090469	51,546198	Nemaska	R18	<Null>	NA9/32N
NA/6-072	0600-2009-556		Mining exploration	-76,275081	51,53686	Nemaska	R18	<Null>	NA6/32N
NA/6-077	0600-2009-557		Mining exploration	-76,288765	51,526118	Nemaska	R18	<Null>	NA7/32N
NA/6-093	0600-2009-558		Mining exploration	-75,876783	51,666305	Nemaska	R18	<Null>	NA102/32O
NA/6-095	0600-2009-559		Mining exploration	-75,559298	51,713044	Nemaska	R20	CAT II	NA6/32O
NA/6-096	0600-2009-560		Mining exploration	-75,55714	51,700594	Nemaska	R20	CAT II	NA5/32O
OB/7-012	0600-2009-561	Manquant	Mining exploration	-75,206758	50,034625	Ouje-Bougoumou	O53	CAT II	OJ03/32Iso
OB/7-017	0600-2009-562		Mining exploration	-74,913879	50,007468	Ouje-Bougoumou	O53	CAT II	OJ01/32Ise
OB/7-043	0600-2009-563		Mining exploration	-74,172735	49,82171	Ouje-Bougoumou	O59	<Null>	MI116/32I
OB/7-059	0600-2009-564		Mining exploration	-74,498134	49,476438	Ouje-Bougoumou	O60	<Null>	OJ01/32Gse
WJ/6-004	0600-2009-565		Mining exploration	-77,725107	53,189648	Wemindji	VC12	CAT II	WJ15/33F
WJ/6-008	0600-2009-566		Mining exploration	-77,229881	53,362517	Wemindji	VC16	<Null>	WJ03/33F
WJ/6-009	0600-2009-567		Mining exploration	-77,304363	53,352605	Wemindji	VC16	<Null>	WJ04/33F
WJ/6-028	0600-2009-568		Mining exploration	-76,683029	53,407059	Wemindji	VC20	<Null>	WJ11/33F
WJ/6-032	0600-2009-569		Mining exploration	-75,874544	53,278277	Wemindji	VC21	<Null>	WJ05/33G
WJ/6-043	0600-2009-570		Mining exploration	-75,673799	53,571383	Wemindji	VC24	<Null>	WJ10/33G
WJ/6-046	0600-2009-571		Mining exploration	-75,513735	53,473313	Wemindji	VC25	<Null>	WJ12/33G
WJ/6-054	0600-2009-572		Mining exploration	-75,1387	53,470086	Wemindji	VC26	<Null>	WJ08/33G
WK/7-003	0600-2009-573		Mining exploration	-78,726362	50,036258	Washaw Sibi	13	<Null>	WK1/32Lse
WK/7-018	0600-2009-574		Mining exploration	-77,837075	50,901207	Waskaganish	N05	<Null>	WK1/32Kno
WK/7-019	0600-2009-575		Mining exploration	-77,86828	50,909711	Waskaganish	N05	<Null>	WK2/32Kno
WK/7-020	0600-2009-576		Mining exploration	-77,887435	50,90837	Waskaganish	N05	<Null>	WK3/32Kno
WK/7-040	0600-2009-577		Mining exploration	-79,247689	50,914217	Waskaganish	N10A	<Null>	WK11/32Lno
WP/7-013	0600-2009-578		Mining exploration	-76,196603	54,939172	Whapmagoostui	GW09	<Null>	WP2/33K
WP/7-027	0600-2009-579		Mining exploration	-73,260308	54,974436	Whapmagoostui	GW17	<Null>	WP1/33I
WP/7-040	0600-2009-580		Mining exploration	-76,505619	54,723581	Whapmagoostui	GW07	<Null>	
WS/7-002	0600-2009-581		Mining exploration	-76,963104	49,883202	Waswanipi	W01	<Null>	WI31/32Fne
WS/7-021	0600-2009-582		Mining exploration	-76,34697	50,820743	Waswanipi	W05A	<Null>	WI01/32Kne
WS/7-024	0600-2009-583		Mining exploration	-76,650337	50,799963	Waswanipi	W05A	<Null>	WI26/32Kne
WS/7-026	0600-2009-584		Mining exploration	-76,429039	50,708465	Waswanipi	W05C	<Null>	WI20/32Kne
WS/7-028	0600-2009-585		Mining exploration	-76,448977	50,701105	Waswanipi	W05C	<Null>	WI22/32Kne
WS/7-030	0600-2009-586		Mining exploration	-76,514362	50,795169	Waswanipi	W05C	<Null>	WI24/32Kne

WS/7-038	0600-2009-587	Mining exploration	-76,246675	50,680871	Waswanipi	W05D	CAT II	WI10/32Kne
WS/7-051	0600-2009-588	Mining exploration	-77,141056	50,635912	Waswanipi	W06A	<Null>	NA121/32K
WS/7-052	0600-2009-589	Mining exploration	-77,053215	50,714316	Waswanipi	W06A	<Null>	NA123/32K
WS/7-054	0600-2009-590	Mining exploration	-77,092911	50,631291	Waswanipi	W06A	<Null>	WI02/32Kno
WS/7-057	0600-2009-591	Mining exploration	-77,107776	50,4996	Waswanipi	W07	<Null>	NA120/32K
WS/7-068	0600-2009-592	Mining exploration	-76,023208	50,468573	Waswanipi	W10	CAT II	WI51/32Kse
WS/7-074	0600-2009-593	Mining exploration	-76,338976	49,938395	Waswanipi	W11A	CAT II	WI23/32Fne
WS/7-076	0600-2009-594	Mining exploration	-76,538987	49,817553	Waswanipi	W11B	CAT II	W21/32Fne
WS/7-077	0600-2009-595	Mining exploration	-76,618416	49,791624	Waswanipi	W11B	CAT II	WI22/32Fne
WS/7-078	0600-2009-596	Mining exploration	-76,545703	49,822885	Waswanipi	W11B	CAT II	WI25/32Fne
WS/7-089	0600-2009-597	Mining exploration	-77,26439	49,892463	Waswanipi	W13	<Null>	WI17/32Fno
WS/7-094	0600-2009-598	Mining exploration	-77,484768	49,712779	Waswanipi	W13A	<Null>	WI03/32Fno
WS/7-100	0600-2009-599	Mining exploration	-76,030295	49,781688	Waswanipi	W15	CAT II	WI11/32Fne
WS/7-103	0600-2009-600	Mining exploration	-75,306084	49,892581	Waswanipi	W16	<Null>	WI02/32Gno
WS/7-104	0600-2009-601	Mining exploration	-75,255697	49,929712	Waswanipi	W16	<Null>	WI03/32Gno
WS/7-105	0600-2009-602	Mining exploration	-75,26177	49,924974	Waswanipi	W16	<Null>	WI04/32Gno
WS/7-126	0600-2009-603	Mining exploration	-75,851073	49,595274	Waswanipi	W21	<Null>	WI12/32Gno
WS/7-134	0600-2009-604	Mining exploration	-75,490396	50,001785	Waswanipi	W22	<Null>	WI01/32Jso
WS/7-136	0600-2009-605	Mining exploration	-75,411566	49,99147	Waswanipi	W22	<Null>	WI03/32Gno
WS/7-137	0600-2009-606	Mining exploration	-75,646713	49,9026	Waswanipi	W22	<Null>	WI04/32Gno
WS/7-142	0600-2009-607	Mining exploration	-74,894528	49,494605	Waswanipi	W23A	<Null>	WI01/32Gse
WS/7-143	0600-2009-608	Mining exploration	-74,886481	49,427858	Waswanipi	W23A	<Null>	WI02/32Gse
WS/7-144	0600-2009-609	Mining exploration	-74,836103	49,584358	Waswanipi	W23A	<Null>	WI03/32Gne
WS/7-145	0600-2009-610	Mining exploration	-74,698416	49,554084	Waswanipi	W23A	<Null>	WI04/32Gne
WS/7-154	0600-2009-611	Mining exploration	-76,522452	49,213043	Waswanipi	W24B	<Null>	WI07/32Fse
WS/7-168	0600-2009-612	Mining exploration	-75,156975	49,419799	Waswanipi	W27	<Null>	WI02/32Gso
WS/7-174	0600-2009-613	Mining exploration	-75,266143	49,490622	Waswanipi	W27	<Null>	WI20/32Gso
WS/7-175	0600-2009-614	Mining exploration	-75,36644	49,524115	Waswanipi	W27	<Null>	WI22/32Gno
WS/7-176	0600-2009-615	Mining exploration	-75,296244	49,492625	Waswanipi	W27	<Null>	WI2/32Gso
WS/7-177	0600-2009-616	Mining exploration	-75,306097	49,483145	Waswanipi	W27	<Null>	WI24/32Gso
WS/7-178	0600-2009-617	Mining exploration	-75,318069	49,473658	Waswanipi	W27	<Null>	WI25/32Gso
WS/7-179	0600-2009-618	Mining exploration	-75,24592	49,481444	Waswanipi	W27	<Null>	WI26/32Gso
WS/7-183	0600-2009-238	Mining exploration	-76,169608	49,496031	Waswanipi	W24A	<Null>	<Null>



Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 20, 2021 1:46 PM

Site Information

Site Number: MI/6-084

Community: Mistissini

Inventory by: Adario Masty

Date and Time: July 3, 2021 3:06 PM

Distance from surface water (m): 20

Soil :

Drainage :

Site size (hectares):
1.2238867653212389

Site Location:



Maxar | Cree Nation Government | Esri Community ... Powered by

Drums

Nb total: 8

Content: Jet Fuel **Name of other:**

Gas	Jet Fuel	Diesel	Oil	Grease	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full: 8	Nb of full:	Nb of full:	Nb of full:	Nb of full:

Distance from a sensitive area (m): Less than 50 m

Photo Drums:



Reservoirs				
Nb total:				
Content: Name of other:				
Gas	Jet Fuel	Diesel	Oil	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:
Distance from a sensitive area (m):				
Photo Reservoirs:				

Propane Tanks		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Propane tanks:		

Batteries		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Batteries:		

Transformers		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Transformers:		



Infrastructures	
Nb Cabin: Condition:	Nb Tent: Condition:
Photo Infrastructures:	

Machinery and Equipment							
Machinery: Name of other:							
Nb of Bulldozer:	Nb of Tractor:	Nb of Truck:	Nb of Conveyor:	Nb of Crusher:	Nb of Muskeg:	Nb of Generator:	Nb of Other:
Distance from a sensitive area (m):							
Photo Machinery:							

Solid Waste and Dry Material (m³ = cubic meters)							
Material: Name of Other:							
Nb of Core Sampling:	Nb of Wood:	Nb of Plastic:	Nb of Metal:	Nb of Rods:	Nb of Cables:	Nb of Garbage:	Nb of Other:
Distance from a sensitive area (m):							
Photo Waste:							

Evidence of Contamination



Yes/No: No	Contamination Description:
Other Information : Couldn't land but tally man confirmed he recently inspected and drums were full. Can easily be cleaned once landing pad is made.	
Photo Contamination:	

Other Photo:





Site Characterization Report

Submitted By: amasty_cng **Submitted Time:** July 4, 2021 7:57 PM

Site Information

Site Number: MI/6-087

Community: Mistissini

Inventory by: Adario Masty

Date and Time: July 3, 2021 9:49 AM

Distance from surface water (m): 30

Soil :

Drainage :

Site size (hectares):
1.2250259532352048

Site Location:



Maxar | Cree Nation Government | Esri Community ... Powered by

Drums

Nb total: 10

Content: Diesel **Name of other:**

Gas	Jet Fuel	Diesel	Oil	Grease	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	8 Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	2 Nb of full:	Nb of full:	Nb of full:	Nb of full:

Distance from a sensitive area (m): Less than 50 m

Photo Drums:



Reservoirs				
Nb total:				
Content: Name of other:				
Gas	Jet Fuel	Diesel	Oil	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:
Distance from a sensitive area (m):				
Photo Reservoirs:				

Propane Tanks		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Propane tanks:		

Batteries		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Batteries:		

Transformers		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Transformers:		



Infrastructures	
Nb Cabin: Condition:	Nb Tent: Condition:
Photo Infrastructures:	

Machinery and Equipment							
Machinery: Name of other:							
Nb of Bulldozer:	Nb of Tractor:	Nb of Truck:	Nb of Conveyor:	Nb of Crusher:	Nb of Muskeg:	Nb of Generator:	Nb of Other:
Distance from a sensitive area (m):							
Photo Machinery:							

Solid Waste and Dry Material (m3 = cubic meters)							
Material: Metal Name of Other:							
Nb of Core Sampling:	Nb of Wood:	Nb of Plastic:	Nb of Metal:	Nb of Rods:	Nb of Cables:	Nb of Garbage:	Nb of Other:
Distance from a sensitive area (m): Less than 50 m							
Photo Waste:							

Evidence of Contamination



Yes/No: No	Contamination Description:
Other Information : Camp reclaimed by nature, old stove pipes and other metal pieces. Very rusty. Helicopter can land on the point. Could be cleaned in 1 day by sling with 2 workers .s\	
Photo Contamination:	

Other Photo:















Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 19, 2021 6:09 PM

Site Information

Site Number: MI/6-090

Community: Mistissini

Inventory by: Adario Masty

Date and Time: July 3, 2021 1:25 PM


Distance from surface water (m): 1

Soil :

Drainage :

Site size (hectares):
0.1379474021019611

Site Location:



Maxar | Cree Nation Government | Esri Community ... Powered by

Drums

Nb total: 11

Content: Name of other:

Gas	Jet Fuel	Diesel	Oil	Grease	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:

Distance from a sensitive area (m): Less than 50 m

Photo Drums:



Reservoirs				
Nb total:				
Content: Name of other:				
Gas	Jet Fuel	Diesel	Oil	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:
Distance from a sensitive area (m):				
Photo Reservoirs:				

Propane Tanks		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Propane tanks:		

Batteries		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Batteries:		

Transformers		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Transformers:		



Infrastructures	
Nb Cabin: Condition:	Nb Tent: Condition:
Photo Infrastructures:	

Machinery and Equipment							
Machinery: Name of other:							
Nb of Bulldozer:	Nb of Tractor:	Nb of Truck:	Nb of Conveyor:	Nb of Crusher:	Nb of Muskeg:	Nb of Generator:	Nb of Other:
Distance from a sensitive area (m):							
Photo Machinery:							


Solid Waste and Dry Material (m3 = cubic meters)							
Material: Name of Other:							
Nb of Core Sampling:	Nb of Wood:	Nb of Plastic:	Nb of Metal:	Nb of Rods:	Nb of Cables:	Nb of Garbage:	Nb of Other:
Distance from a sensitive area (m):							
Photo Waste:							

Evidence of Contamination



Yes/No: No	Contamination Description:
Other Information : Couldn't land, to many trees . Need to cut a pad or go by float plane . Need to go back to check if drums are empty	
Photo Contamination:	

Other Photo: 
--







Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 1, 2021 10:46 PM

Site Information

Site Number: MI/6-106

Community: Mistissini

Inventory by: Adario Masty

Date and Time: July 1, 2021
10:41 PM


**Distance from surface water
(m):** 10

Soil :

Drainage :

Site size (hectares):
0.1924066606789832

Site Location:



Maxar | Cree Nation Government | Esri Community ... Powered by

Drums

Nb total: 2

Content: Other **Name of other:**

Gas	Jet Fuel	Diesel	Oil	Grease	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:

Distance from a sensitive area (m): Less than 50 m

Photo Drums:



Reservoirs				
Nb total:				
Content: Name of other:				
Gas	Jet Fuel	Diesel	Oil	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:
Distance from a sensitive area (m):				
Photo Reservoirs:				

Propane Tanks		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Propane tanks:		

Batteries		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Batteries:		

Transformers		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Transformers:		



Infrastructures	
Nb Cabin: Condition:	Nb Tent: Condition:
Photo Infrastructures:	

Machinery and Equipment							
Machinery: Name of other:							
Nb of Bulldozer:	Nb of Tractor:	Nb of Truck:	Nb of Conveyor:	Nb of Crusher:	Nb of Muskeg:	Nb of Generator:	Nb of Other:
Distance from a sensitive area (m):							
Photo Machinery:							

Solid Waste and Dry Material (m3 = cubic meters)							
Material: Name of Other:							
Nb of Core Sampling:	Nb of Wood:	Nb of Plastic:	Nb of Metal:	Nb of Rods:	Nb of Cables:	Nb of Garbage:	Nb of Other:
Distance from a sensitive area (m):							
Photo Waste:							

Evidence of Contamination



Yes/No: No	Contamination Description:
Other Information : 2 old drums on site , unsafe to land , took pictures. Tall man says drums are empty	
Photo Contamination:	

Other Photo:





Site Characterization Report

Submitted By: amasty_cng Submitted Time: July 1, 2021 10:28 PM

Site Information

Site Number: MI/6-113

Community: Mistissini

Inventory by: Adario Masty

Date and Time: July 1, 2021
11:32 AM

**Distance from surface water
(m):** 5

Soil :

Drainage :

Site size (hectares):
1.1660639462487565

Site Location:



Maxar | Cree Nation Government | Esri Community ... Powered by

Drums

Nb total: 8

Content: Name of other:

Gas	Jet Fuel	Diesel	Oil	Grease	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:

Distance from a sensitive area (m): Less than 50 m

Photo Drums:



Reservoirs				
Nb total:				
Content: Name of other:				
Gas	Jet Fuel	Diesel	Oil	Other
Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:	Nb of empty:
Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:	Nb of partial:
Nb of full:	Nb of full:	Nb of full:	Nb of full:	Nb of full:
Distance from a sensitive area (m):				
Photo Reservoirs:				

Propane Tanks		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Propane tanks:		

Batteries		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Batteries:		

Transformers		
Nb total:		
Nb Good condition:	Nb Fair condition:	Nb Bad Condition:
Distance from a sensitive area (m):		
Photo Transformers:		



Infrastructures	
Nb Cabin: Condition:	Nb Tent: Condition:
Photo Infrastructures:	

Machinery and Equipment							
Machinery: Name of other:							
Nb of Bulldozer:	Nb of Tractor:	Nb of Truck:	Nb of Conveyor:	Nb of Crusher:	Nb of Muskeg:	Nb of Generator:	Nb of Other:
Distance from a sensitive area (m):							
Photo Machinery:							

Solid Waste and Dry Material (m3 = cubic meters)							
Material: Name of Other:							
Nb of Core Sampling:	Nb of Wood:	Nb of Plastic:	Nb of Metal:	Nb of Rods:	Nb of Cables:	Nb of Garbage:	Nb of Other:
Distance from a sensitive area (m):							
Photo Waste:							

Evidence of Contamination



Yes/No: No	Contamination Description:
Other Information : 5 drums in one spot in fair condition. 3 other drums spread out along shore.	
Photo Contamination:	

Other Photo:









Sites deemed active but have waste or debris on trapline M16

Site# MI/6-062

Region

Mistissini

Nb total of Drums

1

Nb total of Batteries

5

Drums

Content

- **Other**

Other

Nb of empty

1

Distance from a sensitive area (m)

Less than 50 m

Batteries

Batteries condition

- **Bad**

Nb bad Batteries

5

Distance from a sensitive area (m)

Less than 50 m

Infrastructures

Nb Cabin

1

Cabin Condition

- **Bad**

Machinery and Equipment

Machinery and Equipment

- **Other**

Solid Waste and Dry Material

Solid Waste and Dry Material

- **Core Sampling**
- **Rods**
- **Debris and domestic garbage**
- **Plastic**
- **Metal**
- **Cables**







Site Number

MI/6-069

Nb total of Drums

16

Drums

Content

- **Diesel**



Site Number

MI/21-326

Nb total of Drums

10 empty

Nb total of Propane tanks

3

1 fridge , 1 hot water tank,1 washing machine,1 water pump. Belonged to a company named Dios about 16 years ago according to tallyman.





Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 20, 2021, 1:46:07 p.m.

Visit Information

Site Number

MI/6-084

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 3, 2021, 3:06:00 p.m.

Site Information

Distance from surface water (m)

20

Site Location

Area: 1.22 Hectares



Maxar

Powered by Esri

Presence of Drums, Tanks, Batteries or Transformer

Nb total of Drums

8

Drums

Content

- **Jet Fuel**

Jet Fuel

Nb of full

8

Distance from a sensitive area (m)

Less than 50 m

Evidence of Contamination

Contamination

No

Other informations

Couldn't land but tally man confirmed he recently inspected and drums were full. Can easily be cleaned once landing pad is made.

mine_site_pts_GlobalID

a7779b97-44e2-4c58-b6b6-082e2a176320

Attachments:



Ada

.jpg

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 19, 2021, 6:09:53 p.m.

Visit Information

Site Number

MI/6-090

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 3, 2021, 1:25:00 p.m.

Site Information

Distance from surface water (m)

1

Site Location

Area: 1,379.47 Sq meters



Powered by Esri

Presence of Drums, Tanks, Batteries or Transformer

Nb total of Drums

11

Drums

Distance from a sensitive area (m)

Less than 50 m

Evidence of Contamination

Contamination

No

Other informations

Couldn't land, to many trees . Need to cut a pad or go by float plane . Need to go back to check if drums are empty

mine_site_pts_GlobalID

c91db2c2-6815-4e37-849d-1c2bb6647e2b

Attachments:



IMG_0284.JPG



IMG_0283.JPG



Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 19, 2021, 4:22:01 p.m.

Visit Information

Site Number

MI/6-091

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 3, 2021, 1:07:00 p.m.

Site Information

Site Location

Area: 6.9 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Nothing on site,flew by area 3 times

mine_site_pts_GlobalID

84d90b5c-fad8-4f2c-a2c1-8c34b3c7f8ff

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 10:59:14 p.m.

Visit Information

Site Number

MI/6-103

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:57:00 p.m.


Site Information

Distance from surface water (m)

20

Site Location

Area: 1.11 Hectares



Infrastructures

Nb Cabin

1

Evidence of Contamination

Contamination

No



Other informations

Old cabin almost all reclaimed by nature. 1 drum was also located about 1 km west of cabin.

mine_site_pts_GlobalID

85fe2179-353d-4c3e-aa05-bfe06c5e0d1c

Attachments:



Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 11:06:40 p.m.

Visit Information

Site Number

MI/6-104

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 1:08:00 p.m.

Site Information

Site Location

Area: 1.29 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Flew sector , nothing visible

mine_site_pts_GlobalID

f5ee410d-26ad-46c4-861f-0739380fa557

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 10:28:13 p.m.

Visit Information

Site Number

MI/6-107

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 11:39:00 a.m.

Site Information

Distance from surface water (m)

20

Site Location

Area: 8,656.94 Sq meters



Maxar

Powered by Esri

Presence of Drums, Tanks, Batteries or Transformer

Nb total of Drums

5

Drums

Distance from a sensitive area (m)

Less than 50 m

Solid Waste and Dry Material

Solid Waste and Dry Material

- **Core Sampling**
- **Metal**

Distance from a sensitive area (m)

Less than 50 m

Evidence of Contamination

Contamination

No

Other informations

5 drums . Tally man checked them before and were empty. Lots of core samples refer tp pictures of core sample racks, lots of small metal cans which looks like napta cans used for cooking and lamps.refer to pictures


mine_site_pts_GlobalID

5f27b5e3-d27f-4ad5-b00e-413b762f053e

Attachments:



Adandoned_Mine_site_p_image-20210701-222405.jpg





IMG_0334.JPG



IMG_0339.JPG



IMG_0336.JPG

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 5:31:00 p.m.

Visit Information

Site Number

MI/6-108

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:30:00 p.m.

Site Information

Distance from surface water (m)

1

Site Location

Area: 9,507.18 Sq meters



Maxar

Powered by Esri

Presence of Drums, Tanks, Batteries or Transformer

Nb total of Drums

21
Drums

Content

- Other

Other

Nb of empty

21

Distance from a sensitive area (m)

Less than 50 m

Solid Waste and Dry Material

Solid Waste and Dry Material

- Other

Material volume (m3)

Distance from a sensitive area (m)

Less than 50 m

Evidence of Contamination

Contamination

No

Other informations

Claude has indicated drums are empty ,more info to be entered, possible cleanup tomorrow with helicopter. Cleaned.

mine_site_pts_GlobalID

8db21bbb-2054-4128-875c-838318b36567

Attachments:





Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 9:09:56 p.m.

Visit Information

Site Number

MI/6-109

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:43:00 p.m.

Site Information

Site Location

Area: 1.96 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Nothing on site,flew by 2 passes

mine_site_pts_GlobalID

72f5baca-91af-47f3-bf43-2eb1e419da20

Abandoned Mine sites

Submitted by: amasty_cng

Submitted time: Jul. 1, 2021, 9:29:16 p.m.

Visit Information

Site Number

MI/6-110

Region

Mistissini

Inventory by

Adario Masty

Date and Time

Jul. 1, 2021, 12:00:00 p.m.

Site Information

Site Location

Area: 6.78 Hectares



Maxar

Powered by Esri

Evidence of Contamination

Contamination

No

Other informations

Nothing on site , several flyby. Cleaned or no longer on site

mine_site_pts_GlobalID

db7a821d-b85f-4391-8831-a21ddcaac9ed



Photo 1



Photo 2

L'épaisseur de
la terre végétale
est très faible
(env. 3 cm)



L'épaisseur de
la terre végétale
est constante
dans toute la
sablière



Endroit: Sablère 32 F13-003

date: 22/08/2000



Vue d'ensemble de la sablière (on regarde vers le sud)

Endroit: Sabliere 32 F13-003

date: 22 / 06 / 2000



Vue d'ensemble de la sabliere (on regarde vers l'ouest)



Endroit: Sablère 32F13-003

date: 22/04/2000



Secteur ou de la terre noire a été extraite (secteur sud-est)
on regarde vers le sud.

Résumé				
Historique	Le gisement été découvert en 1965, il est situé au Nord-Est de la ville de Chibougamau près de Mistissini, feuillet 32I04, Canton O’Sullivan. Exploité de 1967 à 1976 par méthodes souterraines et à ciel ouvert, la production a été de 1 616 567 T de minerai. Ensuite, ce minerai a été traité à l’usine de la mine Principale (île Merrill). Il n’y a pas de parc à résidus mais 7 haldes à stériles et une de magnétite. Substance principale : Cuivre (Cu). Substances secondaires : Zinc (Zn) et Argent (Ag).			
Point de rencontre	Description	Coordonnées UTM nad 83		
		Zone	EST	NORD
	Intersection de la route 167 et du chemin forestier au km 292,5	18 U	586994	5565430
Coordonnées du site minier	Description	Coordonnées UTM nad 83		
		Zone	EST	NORD
	Localisation de la halde à stériles 7	18 U	584464	5565423

Accès au site	
Décrire : - Distance et route - Borne kilométrique ipalité à proximité	De Québec, prendre la route 175 jusqu’à l’intersection des routes 169 et 175 (km 166,3). Tourner à gauche sur la route 169 vers Roberval et La Doré. Prendre la Route 167 Nord jusqu’à la ville de Chibougamau. De Chibougamau, se diriger au Nord avec la route 167 jusqu’au km 292,5. Tourner à gauche et faire 2,8 km sur le chemin Forestier. Traverser le pont et faire 0,3 km pour arriver à la halde à stériles 7. Ensuite pour accéder au site prendre le petit chemin ou sentier aux coordonnées : 584 511 Est, 5566 262 Nord, (marche de 5 minutes).


Photo aérienne 1979



Carte 2016 de SNC Lavallin avec les zones fragiles des piliers de surfaces (couleur jaune)



Carte tenure 2021 publique et privé



Aires d'accumulation (bassin d'eau de mine, halde à stériles, parc à résidus, zone d'épanchement)	
Décrire : - Type et nombre - Coordonnées GPS - Description des résidus miniers - Végétation - Érosion - Débris - Photographie - Commentaires - Drainage - Barrage de castors	Superficie A : - Coordonnées : 584604 Est, 5565823 Nord _____ hauteur : 3 à 10 mètres - Photos : IS-2018-06-28-004, IS-2023-08-29-005 - Notes : égalisée, végétation très faible. (halde 1, 2 et 3). _____ superficie : 24 677 m². Superficie B : - Coordonnées : 584923 Est, 5565827 Nord _____ hauteur : 3 à 10 mètres - Photos : IS-2017-10-25-007, IS-2020-06-04-009, IS-2023-08-29-002 - Notes : égalisée, végétation faible à moyenne (halde 4, fondations et débris) _____ superficie : 70 001 m². Concentré de magnétite : - Coordonnées : 584999 Est, 5565849 Nord _____ hauteur : 2 mètres. - Photo : IS-2020-06-04-010 - Notes : situé à l'Est de la superficie B _____ superficie : 1 984 m². Halde à stériles 1 : - Coordonnées : 584552 Est, 5565918 Nord _____ hauteur : 4 mètres - Photos : IS-2018-06-28-004, IS-2023-08-29-005-006 - Notes : en tas _____ superficie : 1 324 m². Halde à stériles 2 : - Coordonnées : 584601 Est, 5565878 Nord _____ hauteur : 4 mètres - Photos : IS-2018-06-28-004, IS-2023-08-29-005-007 - Notes : en tas _____ superficie : 2 453 m². Halde à stériles 3 : - Coordonnées : 584654 Est, 5565785 Nord _____ hauteur : 3 mètres - Photos : IS-2018-06-28-004, IS-2023-08-29-005-008 - Notes : en tas _____ superficie : 2 273 m².

Aires d'accumulation (bassin d'eau de mine, halde à stériles, parc à résidus, zone d'épanchement)

Décrire : - Type et nombre - Coordonnées GPS - Description des résidus miniers - Végétation - Érosion - Débris - Photographie - Commentaires - Drainage - Barrage de castors	Halde à stériles 4 : - Coordonnées : 584808 Est, 5565712 Nord _____ hauteur : 4,5 mètres - Photos : IS-2020-06-04-007 - Notes : égalisée, inclut chemin qui se rend aux chantiers ouverts 1 et 2. _____ superficie : 4 147 m2. Halde à stériles 5 : - Coordonnées : 584971 Est, 5565712 Nord _____ hauteur : 3 à 5 mètres - Photos : IS-2020-06-04-012 - Notes : égalisée, végétation densité moyenne _____ superficie : 11 789 m². Halde à stériles 6 : - Coordonnées : 584901 Est, 5565315 Nord _____ hauteur : 4 mètres - Photos : IS-2020-06-04-024 - Notes : égalisée, végétation de densité moyenne _____ superficie : 7 253 m². Halde à stériles 7 : - Coordonnées : 584464 Est, 5565423 Nord _____ hauteur : 2 à 3 mètres - Photos : IS-2022-06-07-005-008 - Notes : égalisée, végétation de densité moyenne _____ superficie : 25 915 m².
---	---

Digue (bassin d'eau de mine, halde à stérile, parc à résidus, zone d'épanchement)

- Position et hauteur - Composition - Déversoir - Tour de décantation - Commentaires	Aucune digue sur le site
--	--

Ministère des Ressources naturelles et des Forêts Québec Direction de la restauration des sites miniers	Fiche d'inspection des sites miniers Région 10 : Nord-du-Québec Coba : 8341-0591	ICON SULLIVAN	2023-08-29
--	--	--------------------------	-----------------------

Drainage du site et réseau hydrique

Décrire :

- Canaux
- Barrage de castors
- Ponceaux
- Commentaires

- Pas de barrage de castors dans la rivière Waconachi.
- **Rivière Waconachi** : la rivière a été détournée vers 1967 pour l'exploitation du site qui coule du sud vers le nord.

Infrastructures (la hauteur inclut la partie dans le sol)

Décrire :

- Bâtiments
- Fondations
- Clôture ceinturant le site

- Une clôture non conforme autour de l'ouverture nommé Back fill plant.

Fondation de béton (1) :

- Coordonnées : 584842 Est, 5565851 Nord _____ hauteur : 0,65 mètre
- Photo : **IS-2017-10-25-004**
- Notes : à démolir et à enterrer _____ superficie : 521 m².

Fondation de béton (2) :

- Coordonnées : 584797 Est, 5565774 Nord _____ hauteur : 0,40 m.
- Photo : **IS-2017-10-25-003, IS-2020-06-04-008**
- Notes : à démolir et à enterrer _____ superficie : 1 654 m².

Fondation de béton (3) :

- Coordonnées : 584961 Est, 5565796 Nord _____ hauteur : 0,60 mètre
- Photo : **IS-2017-10-25-006**
- Notes : à démolir et à enterrer _____ superficie : 122 m².

Infrastructures (la hauteur inclut la partie dans le sol)

Décrire : - Bâtiments - Fondations - Clôture ceinturant le site	Fondation de béton (4) : - Coordonnées : 584949 Est, 5565916 Nord _____ hauteur : 0,45 mètre - Photo : IS-2017-10-25-005 - Notes : à démolir et à enterrer _____ superficie : 521 m². Deux bases de béton (5) : - Coordonnées : 585291 Est, 5566238 Nord _____ hauteur : 0,45 mètre - Photo : IS-2023-08-29-001 - Notes : à démolir et à enterrer _____ superficie : 521 m². Base de béton (6) : - Coordonnées : 585299 Est, 5565305 Nord _____ hauteur : 1,15 mètre - Photo : IS-2022-06-07-001 - Notes : à démolir et à enterrer _____ superficie : 8 m2. Fondation de béton (7) : - Coordonnées : 584873 Est, 5565759 Nord _____ hauteur : 0,35 mètre - Photo : IS-2017-10-25-007 - Notes : à démolir et à enterrer _____ superficie : 20 m².
--	--


Matière dangereuse, déchets et contamination

	Aucune.
--	---

Ouverture minière (puits, cheminée, fosse, chantier ouvert, rampe, galerie à flanc de coteau (adit), etc.)					
Type	Chantier ouvert 1	Chantier ouvert 2	Chantier ouvert 3	Affaissement (Backfill Plant)	Puits ventilation 1
Photographie	IS-2018-06-28-005 IS-2020-06-04-006 IS-2023-08-29-005	IS-2018-06-28-008	IS-2018-06-28-003	IS-2018-06-28-006 IS-2018-06-28-007	IS-2023-08-29-003
Coordonnées Gps	584667 Est 5565679 Nord	584812 Est 5565575 Nord	584385 Est 584385 Nord	584884 Est 5565745 Nord	584461 Est 5566591 Nord
Sécurisation	Conforme ? Aucune	Conforme ? Aucune	Conforme ? Aucune	Non Conforme Clôture pour moutons	Conforme Dalle de béton
Relevé Gps points Superficie Profondeur Longueur de clôture Notes	55 à 61 22 343 m² 600 mètres N/D 600 mètres	62 à 74 47 687 m² 1200 mètres N/D 1200 mètres	137 à 144 26 693 m² 685 mètres N/D 685 mètres	75 à 78 1 140 m² 164 mètres 8 mètres 164 mètres	136 Nil Côté Nord du Chantier Ouvert 3
Remarques 2022	Pas de changements	Pas de changements	Pas de changements	Pas de changements	Pas de changements

Ouverture minière (puits, cheminée, fosse, chantier ouvert, rampe, galerie à flanc de coteau (adit), etc.)					
Type	Puits de ventilation 2				
Photographie	Op-2020-06-04-011				
Coordonnées GPS	Secteur 584926 Est 5565725 Nord				
Sécurisation	Remblayé Conforme				
Relevé Gps Situé	IS-PV-2 Au Sud-Est du back fill plant				
Remarques 2022	Pas de changements				

Schéma de localisation



Ministère des Ressources naturelles et des Forêts Québec Direction de la restauration des sites miniers	Fiche d'inspection des sites miniers Région 10 : Nord-du-Québec Coba : 8341-0591	ICON SULLIVAN	2023-08-29
--	--	--------------------------	-----------------------

Travaux réalisés

	• Les haldes à stériles 4 à 7 sont égalisées et en végétation naturelle de densité faible. • Les deux dalles de béton sur les deux puits de ventilation. • L'affaissement nommé Backfill Plant est entouré d'une clôture de broche en bon état mais non-conforme. • Étude de caractérisation phase 1 a débuté en depuis 2015 • Août 2023 : 8 affiches "Risque d'instabilité du sol" ont été installées par le MERN.
--	---

Travaux à réaliser (priorité)

	• Terminer les phases 2 et 3 de l'étude de caractérisation. • Remblayer le chantier souterrain défoncé nommé « Backfill Plant ». • Égaliser les haldes à stériles 1-2-3 et remettre le site en végétation. • Démolir, enterrer les fondations de béton et ramasser les débris de métal pour le recyclage.
--	---

Remarques spécifiques

	• Les coordonnées sont en UTM Nad 1983. • Accompagné d'Alexandre Dubé Couturier pour la visite du 4 septembre 2014.
--	---

Rédigé par : Jean-Luc Latulippe 2024-01-11	Original signé	Vérifié par Stephan Grenier	Original signé	2024-01-12
--	----------------	-----------------------------	----------------	------------

Piézomètre	Coordonnées		État	Situé	Remarques	Photos
(#)	EST	NORD	extérieur			(#)
PO-15-01	585346	5566344	Très bon	NE de la fondation (6)		IS-2022-06-07-004
PO-15-02	585205	5566396	Coupé	NW de la fondation (6)	Par le déneigeur hiver 2018	IS-2022-06-07-003
PO-15-03	584528	5565821	Croche	Sentier d'accès superficie A	Cie forestière en 2019	IS-2023-08-29-009
PO-15-05	584443	5566601	Très bon	Près puits ventilation 1		IS-2023-08-29-003
PO-15-06	584443	5566381	Très bon	NW de la halde stériles 7		IS-2022-06-07-008
PO-15-07	585006	5565822	Très bon	Dans la magnétite		IS-2020-06-03-010
PO-15-08	584816	5565918	Très bon	W et 100m de la fondation (4)	Pas de cadenas	IS-2020-06-03-009
PO-15-10	584796	5565802	Très bon	N de la fondation (2)		IS-2020-06-03-008
PO-15-11	584566	5565772	Très bon	NE du chantier ouvert 1		IS-2023-08-29-008
PO-15-12	584613	5565833	Très bon	SW de la halde à stériles 2		IS-2023-08-29-007
PO-15-13	585303	5566303	Très bon	Près de la fondation (6)		IS-2022-06-07-002
PO-15-14	584880	5565442	Très bon	SE de la halde à stériles 5		IS-2020-06-03-011
PO-15-15	584545	5566301	Très bon	SW de la halde à stériles 7		IS-2022-06-07-005
PO-15-16	584664	5565742	Très bon	N du chantier ouvert 1		IS-2020-06-03-006
PO-15-17	584572	5565901	Très bon	SE de la halde à stériles 1	A été coupé depuis 2022	IS-2023-08-29-005-006
PO-15-18	584916	5565903	Très bon	N de la superficie B (ancien pont)		IS-2023-08-29-002
PO-15-19	584908	5565695	Très bon	W et 50m du puits ventilation 2		IS-2020-06-03-014



IS-2018-06-28-003 – Chantier ouvert 3 et le puits de ventilation 1 conforment (vue Ouest vers l'Est) Coordonnées UTM Nad83 : 584456 Est, 5566472 Nord




IS-2018-06-28-004 – Superficie A, avec les haldes à stériles 1,2 et 3 (vue du Nord vers le Sud) Coordonnées UTM Nad83 : 584581 Est, 5565762 Nord




IS-2017-10-25-003 – Fondation de béton (2) (vue vers l'Est)

Coordonnées UTM Nad83 : 584746 Est, 5565763 Nord




IS-2017-10-25-004 – Fondation de béton (1) (vue vers le Nord-Est)

Coordonnées UTM Nad83 : 584820 Est, 5565826 Nord




IS-2017-10-25-005 – Fondation de béton (4) (vue vers l'Ouest)

Coordonnées UTM Nad83 : 584957 Est, 5565913 Nord



IS-2017-10-25-006 – Fondation de béton (3) (vue vers l'Est)


Coordonnées UTM Nad83 : 584947 Est, 5565790 Nord



IS-2017-10-25-007 – Fondation de béton (7) et arrière superficie B
(vue vers le Nord)
Coordonnées UTM Nad83 : 584874 Est, 5565790 Nord



IS-2018-06-28-005 – Du côté Sud-Ouest, vue du chantier ouvert 1
(vue vers le Nord-Est)
Coordonnées UTM Nad83 : 584595 Est, 5565588 Nord




IS-2018-06-28-006 – Du côté Est, affaissement au Backfill Plant
(vue vers l'Ouest)
Coordonnées UTM Nad83 : 584908 Est, 5565749 Nord



IS-2018-06-28-007 – Du côté Ouest, affaissement au Backfill Plant
(vue vers l'Est)
Coordonnées UTM Nad83 : 584861 Est, 5565719 Nord




IS-2018-06-28-008 – Du côté Nord-Ouest, vue du chantier ouvert 2
(vue vers le Sud-Est)
Coordonnées UTM Nad83 : 584657 Est, 5565607 Nord




IS-2020-06-03-006 – Piézomètre **PO-15-16**, en arrière le chantier ouvert 1
(vue vers le Sud-Est)
Coordonnées UTM Nad83 : 584669 Est, 5565756 Nord




IS-2020-06-03-007 – Du côté Sud-Est, vue de la halde à stériles 4
(vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 584865 Est, 5565743 Nord




IS-2020-06-03-008 – Piézomètre **PO-15-10**, en arrière c'est la fondation **(2)**
dans la superficie **B** (vue vers le Sud)
Coordonnées UTM Nad83 : 584794 Est, 5565809 Nord




IS-2020-06-03-009 – Piézomètre **PO-15-08** à 100 m et à l'Ouest de la fondation **(4)** (vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 584813 Est, 5565931 Nord



IS-2020-06-03-010 – Piézomètre **PO-15-07** situé dans la magnétite à l'Ouest dans la superficie **B** (vue vers le Nord)
Coordonnées UTM Nad83 : 585010 Est, 5565817 Nord



IS-2020-06-03-011 – Secteur du puits de ventilation 2, remblayé et situé à 100 m au Sud de Back Fill plant
Coordonnées UTM Nad83 : 584953 Est, 5565732 Nord




IS-2020-06-03-012 – Piézomètre **PO-15-14**, en arrière, le côté Ouest de la halde à stériles 5 (vue vers l'Est)
Coordonnées UTM Nad83 : 584880 Est, 5565444 Nord




IS-2020-06-03-013 – Du côté Nord, vue de la halde à stériles 6
(vue vers le Sud)
Coordonnées UTM Nad83 : 584865 Est, 5565404 Nord



IS-2020-06-03-014 – Piézomètre **PO-15-19**, situé à 50m à l'Ouest du puits
ventilation 2 (vue vers le Nord)
Coordonnées UTM Nad83 : 584911 Est, 5565689 Nord




IS-2022-06-07-002 – Piézomètre **PO-15-13**, en arrière c'est la fondation (6)
(vue vers le Nord)
Coordonnées UTM Nad83 : 585305 Est, 5566302 Nord




IS-2022-06-07-003 – Piézomètre **PO-15-02** coupé au déneigement hiver
2018 (vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 585207 Est, 5566398 Nord



IS-2022-06-07-004 - Piézomètre **PO-15-01** en très bon état
(vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 585340 Est, 5566344 Nord




IS-2022-06-07-005 – Du Sud-Ouest, piézomètre **PO-15-15** et la halde à
stériles 7 (vue vers le Nord-Ouest)
Coordonnées UTM Nad83 : 584531 Est, 5566279 Nord




IS-2022-06-07-008 – Du Nord-Ouest, piézomètre **PO-15-06** et la halde à stériles 7 (vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 584441 Est, 5566377 Nord



IS-20232023-08-29-001 – Affiche Danger sol instable et fondation de béton (5)
(vue vers le Nord)
Coordonnées UTM Nad83 : 585300 Est, 5566212 Nord




IS-2023-08-29-002 – Affiche Danger situé à l'ancien pont enlevé. En arrière le piézomètre **PO-15-18** (vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 584918 Est, 5565944 Nord




IS-2023-08-29-003 – Puits de ventilation 1 conforme et piézomètre **PO-15-05** (vue vers l'Est)
Coordonnées UTM Nad83 : 584462 Est, 5566588 Nord




IS-2023-08-29-004 – 2 affiches Danger situé au chemin d'accès
(vue vers le Sud-Ouest)
Coordonnées UTM Nad83 : 584512 Est, 5566267 Nord




IS-2023-08-28-005 – Piézomètre **PO-15-17** coupé, les haldes 1 et 2 et
chantier ouvert 1 (vue vers le Sud)
Coordonnées UTM Nad83 : 584555 Est, 5565933 Nord




IS-2023-08-2929-006 – Piézomètre **PO-15-17** coupé en arrière halde stériles 1
(vue vers le Nord-Ouest)
Coordonnées UTM Nad83 : 584585 Est, 5565899 Nord



IS-2023-08-29-007 – Piézomètre **PO-15-12**, en arrière la halde à stériles 2
(vue vers le Nord-Est)
Coordonnées UTM Nad83 : 584612 Est, 5565817 Nord



IS-2023-08-29-008 – Superficie **A**, piézo. **PO-15-11**, et la halde à stériles 3
(vue vers l'Est)
Coordonnées UTM Nad83 : 584563 Est, 5565773 Nord



IS-2023-08-29-009 – Piézomètre **PO-15-03**, a été accroché par cie forestière
hiver 2019 (vue vers le Nord-Ouest)
Coordonnées UTM Nad83 : 584527 Est, 5565821 Nord

[Rapport final – Caractérisation environnementale du site minier Icon Sullivan.](#)

Nous vous indiquons que vous pouvez demander à la Commission d'accès à l'information de réviser cette décision. Vous trouverez ci-joint une note explicative concernant l'exercice de ce recours ainsi qu'une copie des articles précités.

Veuillez agréer, Monsieur, l'expression de nos sentiments les meilleurs.

La responsable de l'accès à l'information,

Original signé par

Matilde Thérout-Lemay

p. j. 3